

# **CONTENTS**

1.	INTRODUCTION . . . . .	1
1.1.	Background. . . . .	1
1.2.	Objective . . . . .	2
1.3.	Scope. . . . .	2
1.4.	structure . . . . .	3
2.	B A C K G R O U N D I N F O R M A T I O N . . . . .	3
2.1.	Regulatory infrastructure . . . . .	3
2.1.1.	Competent authority. . . . .	3
2.1.2.	Legal framework . . . . .	4
2.1.3.	Implementation of the regulations. . . . .	6
2.1.4.	Occupational health . . . . .	8
2.2.	Radiography company . . . . .	9
2.3.	Radiography equipment . . . . .	10
3.	CHRONOLOGY OF THE ACCIDENT . . . . .	15
3.1.	In Cochabamba. . . . .	15
3.2.	Bus journey to La Paz . . . . .	18
3.3.	In La Paz . . . . .	19
4.	FOLLOW-UP ACTIONS . . . . .	21
4.1.	Overview o f f o l l o w - u p . . . . .	21
4.2.	I n i t i a l d o s e assessment. . . . .	23
4.3.	I n i t i a l medical a s s e s s m e n t . . . . .	26
4.4.	I d e n t i f y i n g t h e exposed individuals . . . . .	26
5	IAEA RESPONSE . . . . .	31
5.1.	I n i t i a l a c t i o n s . . . . .	31
5.2.	I n v e s t i g a t i o n . . . . .	33
5.3.	A s s e s s m e n t o f d o s e s . . . . .	33
5.3.1.	E x p o s u r e o f t h e I B N O R C A employees . . . . .	33
5.3.2.	E x p o s u r e o f t h e bus passengers . . . . .	36
5.3.3.	E x p o s u r e o f other p e r s o n s . . . . .	41

5.4. Medical assessment and actions taken for reassurance b y t h e I A E A team	43
6. FINDINGS, CONCLUSIONS AND RECOMMENDATIONS	45
6.1. Attainment of mission objectives .....	45
6.2. Lessons to be learned.....	47
6.2.1. Operating organizations .....	47
6.2.2. Regulatory body.....	49
6.2.3. Medical issues.....	50
6.2.4. International bodies. ....	51
REFERENCES .....	51
ANNEX: MEDICAL FORM FOR PERSONS INVOLVED IN THE ACCIDENT‘.....	53
CONTRIBUTORS TO DRAFTING AND REVIEW..	55