

CONTENTS

SUMMARY	1
1. BACKGROUND	1
2. REPORT OF INCIDENTS	4
2.1. Mihama Unit 3 pipe rupture accident in Japan.....	4
2.2. Lessons learned from Davis Besse NPP – reactor pressure vessel degradation	6
2.3. Erosion-corrosion in the secondary system piping and components in Finland.....	8
2.4. Vandellós II – essential service water system pipe degradation.....	10
3. TECHNICAL ISSUES	11
3.1. Status report on material degradation at Paks NPP, Hungary	11
3.2. The Czech Republic erosion-corrosion programme and lessons learned from Mihama NPP	12
3.3. COMSY software to assist lifetime management activities	13
3.4. Guideline for management of piping wall thinning in PWR secondary systems in Japan	14
3.5. PERFECT Program on “Multi-Scale Model of Irradiation of Materials”	15
3.6. Erosion-corrosion monitoring, forecast and control of processes of second circuit of WWER NPPs’ damage due to operating conditions.....	15
4. MANAGERIAL ISSUES	18
4.1. Leibstadt (Switzerland) NPP programme for the prevention of piping degradation due to flow-accelerated corrosion phenomena	18
4.2. Managerial improvement efforts after finding unreported cracks in reactor components.....	19
4.3. Aspects of unexpected events in nuclear power plants	20
4.4. Overview of the French Atomic Energy Commission R&D programme for reactor material ageing phenomena understanding and modelling.....	21
5. REGULATORY ASPECTS	21
5.1. Overview of regulatory aspects of ageing issues of nuclear power plants in Japan.....	21
5.2. Canadian regulatory approach towards ageing management programmes and critical component condition monitoring and evaluation.....	22
6. CONCLUSIONS AND RECOMMENDATIONS.....	23
6.1. Administrative issues.....	23
6.2. Technical/managerial issues	23
6.3. Underlying causes.....	24
6.4. Main recommendations	25

PAPERS PRESENTED AT THE TECHNICAL MEETING

REPORT OF INCIDENTS (SESSION 1)

Summary of the interim report on the secondary system pipe rupture at Unit 3, Mihama Nuclear Power Plant.....	29
<i>T. Wani, Y. Bessho</i>	
Lessons learned – reactor pressure vessel degradation	33
<i>R. Schrauder</i>	
Guillotine breaks of FW lines at Loviisa 440	39
<i>O. Hietanen</i>	
Vandellos II – Essential service water system pipe degradation	49
<i>C.J. Cirauqui</i>	
Service induced degradations of CANDU feeder piping – FAC wall thinning and cracking.....	53
<i>J.C. Jin, A. Blahoianu, T. Viglasky</i>	

TECHNICAL ISSUES (SESSION 2)

Status report on material degradation at Paks NPP	63
<i>F. Oszvald</i>	
The Czech Republic erosion-corrosion programme and lessons learned from Mihama NPP	73
<i>J. Zdarek</i>	
COMSY software assists lifetime management activities	77
<i>R. Roessner, H. Nopper, A. Zander</i>	
Guideline for management of piping wall thinning in PWR secondary systems in Japan	87
<i>N. Chigusa</i>	
Laguna Verde U2 NPP / reactor vessel shroud IGSCC susceptibility assessment and its inspections results.	101
<i>G. Fernandez</i>	

MANAGERIAL ISSUES (SESSION 3)

The KKL program for the prevention of piping degradation due to flow-accelerated corrosion phenomena	107
<i>R. Roessner, P. Buehlmann, K. Siegrist</i>	
Managerial improvement efforts after finding unreported cracks in reactor components	117
<i>S. Kawamura</i>	
Aspects of unexpected events in nuclear power plants	125
<i>P. Tipping</i>	

REGULATORY ASPECTS (SESSION 4)

Overview of regulatory aspects of aging issues of nuclear power plants in Japan	133
<i>K. Takitani</i>	
Canadian regulatory approach towards ageing management programs and critical component condition monitoring and evaluation	143
<i>A. Blahoianu, C. Moses, T. Viglasky</i>	
Impact of reactor pressure vessel degradation	155
<i>R. Schrauder</i>	

Regulatory aspects of aging management in Argentina.....	159
<i>S. Fabbri, M. Chocron, R.A. Versaci</i>	
SPECIAL SESSION (SESSION 5)	
Integrated surveillance specimen program for WWER-1000/V-320 reactor pressure vessels	171
<i>M. Brumovsky, J. Zdarek</i>	
Investigations on the corrosion behaviour of structural materials of PWR primary circuits.....	179
<i>D. Féron, O. Raquet, C. Richet</i>	
FEEDBACK FOR GOOD PRACTICES AND RECOMMENDATIONS.....	189
LIST OF PARTICIPANTS	195