

Contents

Dedication	ii
Preface	vii
Summary	xi

Rule 1. *Achieve a good quality melt* 1

1.1	Background	1
1.2	Melting	3
1.3	Holding	3
1.4	Pouring	4
1.5	Melt treatments	5
1.5.1	Degassing	5
1.5.2	Additions	6
1.6	Filtration	7
1.6.1	Packed beds	7
1.6.2	Alternative varieties of filters	8
1.6.3	Practical aspects	8

Rule 2. *Avoid turbulent entrainment (the critical velocity requirement)* 9

2.1	Maximum velocity requirement	10
2.2	The 'no fall' requirement	13
2.3	Filling system design	15
2.3.1	Gravity pouring of open-top moulds	15
2.3.2	Gravity pouring of closed moulds	16
2.3.3	Horizontal transfer casting	68
2.3.4	Counter-gravity	72
2.3.5	Surface tension controlled filling	75
2.3.6	Inclusion control: filters and traps	78
2.3.7	Practical calculation of the filling system	93

Rule 3. *Avoid laminar entrainment of the surface film (the non-stopping, non-reversing condition)* 102

3.1	Continuous expansion of the meniscus	102
3.2	Arrest of vertical progress	103

3.3	Waterfall flow	104
3.4	Horizontal stream flow	104
3.5	Hesitation and reversal	106

Rule 4. *Avoid bubble damage* 108

4.1	Gravity-filled running systems	111
4.2	Pumped and low-pressure filling systems	112

Rule 5. *Avoid core blows* 114

5.1	Background	114
5.2	Prevention	117

Rule 6. *Avoid shrinkage damage* 120

6.1	Feeding systems design background	120
6.1.1	Gravity feeding	123
6.1.2	Computer modelling of feeding	124
6.1.3	Random perturbations to feeding patterns	124
6.1.4	Dangers of solid feeding	125
6.1.5	The non-feeding roles of feeders	125
6.2	The seven feeding rules	126
Rule 1:	Do not feed	126
Rule 2:	Heat-transfer requirement	127
Rule 3:	Mass-transfer requirement	128
Rule 4:	Junction requirement	132
Rule 5:	Feed path requirement	133
Rule 6:	Pressure gradient requirement	138
Rule 7:	Pressure requirement	140
6.3	The new feeding logic	142
6.3.1	Background	142
6.3.2	The new approach	143
6.4	Active feeding	145
6.5	Freezing systems design	146

6.5.1	External chills	147	10.2.1	Rectilinear systems	177
6.5.2	Internal chills	149	10.2.2	Cylindrical systems	178
6.5.3	Fins	150	10.2.3	Trigonal systems	179
			10.2.4	Thin-walled boxes	179
Rule 7.	<i>Avoid convection damage</i>	157	10.3	Location jigs	180
7.1	Convection: the academic background	157	10.4	Clamping points	180
7.2	Convection: the engineering imperatives	157	10.5	Mould design: the practical issues	181
7.3	Convection damage and casting section thickness	160	10.6	Casting accuracy	182
7.4	Counteracting convection	162	10.7	Tooling accuracy	183
			10.8	Mould accuracy	183
Rule 8.	<i>Reduce segregation damage</i>	163	10.9	Summary of factors affecting accuracy	186
			10.10	Metrology	186
Rule 9.	<i>Reduce residual stress (the 'no water quench' requirement)</i>	166	Appendix	188	
9.1	Introduction	166	The 1.5 factor	188	
9.2	Residual stress from casting	166	The Bernoulli equation	189	
9.3	Residual stress from quenching	167	Rate of pour of steel castings from a bottom-pour ladle	191	
9.4	Distortion	172	Running system calculation record	191	
9.5	Heat treatment developments	173	Design methodology for investment castings	194	
9.6	Epilogue	174	References	195	
Rule 10.	<i>Provide location points</i>	175	Index	199	
10.1	Datums	175			
10.2	Location points	176			