

CONTENTS

1.	INTRODUCTION	1
1.1.	Background	1
1.2.	Objective	2
1.3.	Scope	3
1.4.	Structure	3
2.	BACKGROUND INFORMATION	3
2.1.	Infrastructure for radiation protection in Turkey	3
2.2.	Description of the company	5
2.3.	The radioactive sources and packages	7
3.	THE ACCIDENT	12
3.1.	Initiating events	12
3.2.	Subsequent events	19
4.	RESPONSE TO THE ACCIDENT	23
4.1.	Recovery of the source at the scrapyard	23
4.1.1.	Source recovery operation: Day 1	23
4.1.2.	Source recovery operation: Day 2	25
4.1.3.	Doses received by personnel in the recovery operation	27
4.2.	Initial response to assess public health	28
4.3.	Search for a second source	28
4.4.	The TAEK's response to prevent the recurrence of similar accidents	30
4.5.	Response from the IAEA	31
4.6.	Public concern in Turkey	33
5	SUMMARY OF MEDICAL ASPECTS OF THE ACCIDENT	34
5.1.	Chronology of progression of medical conditions and their management	34
5.2.	Conclusions on the medical treatment	39
6.	SUMMARY OF BIOLOGICAL DOSIMETRIC ANALYSES	40

6.1.	Participating laboratories	40
6.2.	Analysis of dicentrics	41
6.3.	Micronuclei assay	42
6.4.	Translocational analysis by FISH	43
6.5.	Findings from biodosimetry	44
7.	FINDINGS, CONCLUSIONS AND LESSONS TO BE LEARNED	44
7.1.	Operating organizations	44
7.2.	National authorities	45
7.3.	International co-operation	47
7.4.	Equipment suppliers	47
7.5.	Medical community	48
	REFERENCES	51
	ANNEX I: CHRONOLOGY OF EVENTS	53
	ANNEX II: MEDICAL DATA	63
	ANNEX III: BIOLOGICAL DOSE ESTIMATION	71
	CONTRIBUTORS TO DRAFTING AND REVIEW	75