Contents

List of contributors xvii
Abbreviations xx

1. Introduction to defect and microstructure analysis or the analysis of real structure **1**
Jaroslav Fiala and Robert L. Snyder
1.1 Introduction 1
1.2 What is real structure? 2
1.3 X-ray diffraction analysis of real structure 4
1.4 Restoring physical patterns from observed values 8
1.5 Conclusions 10
1.6 References 10

Part I. Fundamentals of defect analysis by diffraction **17**

2. Some applications of the kinematical theory of X-ray diffraction **19**
Hans Bradaczek
2.1 Introduction 19
2.2 The basis of the kinematical theory 19
2.3 Bragg's law 21
2.4 Direct methods of phase determination 22
2.5 Particle size effect 24
2.6 Convolution square root 25
2.7 Influence of the periodic elements (atoms, clusters) 26
2.8 General epilogue 27
2.9 References 28

3. Profile fitting and analytical functions **29**
Stefano Enzo and Liliana Schiffini
3.1 Historical presentation of the theoretical framework 29
3.2 The selection and the mathematical properties of the line shape function 31
3.3 The use of line shape parameters in practical cases 36
3.4 Conclusions 39
3.5 References 40

4. Effects of instrument function, crystallite size, and strain on reflection profiles **41**
V. Honkimäki and P. Suortti
4.1 Introduction 41
4.2 Total pattern 42

4.3 Instrument function 43
4.4 Modeling of background 45
4.5 Crystallite size and strain 52
4.6 Anisotropic strain and particle size 54
4.7 Summary 56
4.8 References 56
Appendix 1. Spherical harmonics 56

5. Use of pattern decomposition or simulation to study microstructure: theoretical considerations 59
J. Ian Langford
5.1 Introduction 59
5.2 Diffraction effects due to crystallite or domain size 63
5.3 Diffraction effects due to structural 'mistakes' 68
5.4 Interpretation of apparent strain 70
5.5 Characterization of microstructure 72
5.6 References 76
Appendix 1. Analytical functions commonly used to model powder diffraction line profiles 77
Appendix 2. Apparent and 'true' size of crystallites or domains from the integral breadth 79

6. Classical treatment of line profiles influenced by strain, small size, and stacking faults 82
C.R. Houska and R. Kužel
6.1 Introduction 82
6.2 Classical treatment 83
6.3 Discussion 92
6.4 References 93

7. Voigt function model in diffraction-line broadening analysis 94
Davor Balzar
List of symbols 94
7.1 Introduction 95
7.2 Diffraction-line broadening 97
7.3 Size–strain analysis 108
7.4 Concluding remarks 123
7.5 References 124

8. X-ray analysis of precipitation-related crystals with dislocation substructure 127
R.I. Barabash
8.1 References 140

9. Analytic functions describing line profiles influenced by size distribution, strain, and stacking faults **141**
C.R. Houska and R. Kužel
9.1 Introduction 141
9.2 Correlated dislocations 147
9.3 Analytic profiles 150
9.4 General analytic method 151
9.5 Discussion 159
9.6 References 160
Appendix 1 161
Appendix 2. Krivoglaz expansion of strain 163
Appendix 3. Column distances, conversions, units 163

10. The dislocation-based model of strain broadening in X-ray line profile analysis **165**
T. Ungár
10.1 Introduction 165
10.2 The theory of strain broadening 167
10.3 Experimental aspects 179
10.4 Single-profile measurements and results 181
10.5 Two-profile analysis of the dislocation structure 182
10.6 The analysis of small grain specimens 190
10.7 Conclusions 195
10.8 References 196

11. Diffraction-line broadening analysis of dislocation configurations **200**
A.C. Vermeulen, R. Delhez, Th.H. de Keijser, and E.J. Mittemeijer
11.1 Introduction 200
11.2 Integral breadths and Fourier coefficients: previous work 200
11.3 Theory of diffraction-line broadening by dislocations 201
11.4 How to deal with eqn (8) 205
11.5 [111] Fibre-textured f.c.c metal layers plastically deformed by thermal stresses 207
11.6 Practical example: aluminium layers 209
11.7 Summary 212
11.8 References 213

12. Diffraction-line broadening analysis of strain fields in crystalline solids **214**
J.G.M. van Berkum, R. Delhez, Th.H. de Keijser, and E.J. Mittemeijer
12.1 Introduction 214
12.2 Basic considerations and scope of the chapter 214
12.3 Line profile description 217
12.4 Line profile decomposition: resolving size and strain 218

12.5 Line profile synthesis and matching: refining microstructure parameters 222
12.6 Order dependence of line broadening: evaluation of line profile decomposition methods 226
12.7 Line profile syntheses and matching: practical example 228
12.8 Summary 231
12.9 References 232

13. Paracrystallinity 234
Hans Bradaczek
13.1 Introduction 234
13.2 The basic idea 234
13.3 The real paracrystal 238
13.4 Computer simulation of paracrystals 239
13.5 Summary 245
13.6 References 245

14. The model of the paracrystal and its application to polymers 247
W. Wilke
14.1 Introduction 247
14.2 Ideal paracrystal 248
14.3 Scattering intensity of ideal paracrystals 250
14.4 Examples of application of the method to polymers 254
14.5 Some remarks about paracrystal models for the interpretation of small-angle scattering 262
14.6 References 262

15. Effect of planar defects in crystals on the position and profile of powder diffraction lines 264
A.I. Ustinov
15.1 Introduction 264
15.2 Equation for intensity calculation and common law of X-ray scattering crystals with planar defects 265
15.3 Planar defects in body-centered cubic (body-centered tetragonal and body-centered rhombohedral) lattices 269
15.4 Planar defects in crystals with face-centered cubic lattices 285
15.5 Planar defects in hexagonal close-packed crystals 299
15.6 One-dimensionally disordered crystals with long periods 309
15.7 Conclusions 315
15.8 References 316

16. Effect of stacking disorder on the profile of the powder diffraction line 318
Z. Weiss and P. Čapková
16.1 Introduction 318

16.2 Translation stacking faults 318
16.3 Diffraction patterns 320
16.4 Results of calculations 322
16.5 References 328

Part II. Experimental techniques **331**

17. Crystallite statistics and accuracy in powder diffraction intensity measurements **333**
Deane K. Smith
17.1 Introduction 333
17.2 Intensity measurement 335
17.3 Crystallite statistics 336
17.4 Crystallite statistics in diffractometer geometry 338
17.5 Crystallite statistics for other instruments 343
17.6 Summary 344
17.7 References 345

18. Reciprocal space mapping and ultra-high resolution diffraction of polycrystalline materials **346**
Paul F. Fewster and Norman L. Andrew
18.1 Introduction 346
18.2 Why high resolution? 346
18.3 The diffraction equipment 348
18.4 Conventional methods 350
18.5 Three-dimensional diffraction in practice 352
18.6 Practical examples of three-dimensional diffraction 355
18.7 Summary 362
18.8 References 363

Part III. Macrostress **365**

19. X-ray analysis of the inhomogenous stress state **367**
I. Kraus and N. Ganev
19.1 Introduction 367
19.2 Basic elements of X-ray stress measurement 367
19.3 The actual residual state of stress in products is inhomogenous 372
19.4 Stress gradient 376
19.5 Non-uniform stress problems solved by X-ray at Czech TU in Prague 379
19.6 Conclusions 400
19.7 References 401

Part IV. Texture **403**

20. Texture and structure of polycrystals **405**
Hans J. Bunge
List of symbols 405
20.1 Introduction 411
20.2 Structure of polycrystalline materials 412
20.3 Correspondence of structure in reciprocal space 415
20.4 Problems to be considered in texture analysis 427
20.5 Definition of the texture 428
20.6 Symmetries of the texture functions 433
20.7 Statistical relevance of the texture functions 436
20.8 The texture degree 438
20.9 Calculation of the ODF from experimental data 438
20.10 Compatibility of pole figures (measures of error) 441
20.11 Series expansion 442
20.12 Special distribution functions 446
20.13 Experimental methods of texture analysis 448
20.14 Generalized textural quantities 489
20.15 Applications of texture analysis 495
20.16 References 513

21. Texture effects in powder diffraction and their correction by simple empirical functions **520**
V. Valvoda
21.1 Introduction 520
21.2 Simple texture characterization and correction 521
21.3 Theory 521
21.4 Experimental 524
21.5 Summary 528
21.6 References 530

Part V. Whole-pattern fitting **533**

22. Accounting for size and microstrain in whole-powder pattern fitting **535**
A. Le Bail
List of symbols 535
22.1 Introduction 535
22.2 Theory 538
22.3 WPPF with direct quantitative account for S/M effects 541
22.4 WPPF with qualitative accounts for S/M effects 544
22.5 Two experimental illustrations which qualitatively account for S/M in WPPF 547
22.6 Conclusions 552
22.7 References 552

23. Modelling of texture in whole-pattern fitting **556**
Matti Järvinen
23.1 Introduction 556
23.2 Orientation distribution of grains 556
23.3 Integrated intensity 558
23.4 The harmonic model 560
23.5 Symmetrized harmonics 561
23.6 Examples 562
23.7 Further simplifications 563
23.8 Rietveld method 568
23.9 Discussion 568
23.10 References 569

24. A new whole-powder pattern-fitting approach **570**
P. Scardi
24.1 Introduction 570
24.2 Methodology 572
24.3 Applications 578
24.4 Conclusions 593
24.5 References 594

25. The role of whole-pattern databases in materials science **597**
Deane K. Smith
25.1 Introduction 597
25.2 The nature of the diffraction pattern 598
25.3 Defining pattern parameters for a whole-pattern databases 601
25.4 The role of calculated and simulated patterns in a whole-pattern database 603
25.5 A database for the analysis of clay minerals 603
25.6 Uses of the Clay Minerals Database 606
25.7 Future of whole-pattern databases 606
25.8 Summary 608
25.9 References 609

Part VI. Restoring physical patterns from the observed variables **611**

26. Restoration and preprocessing of physical profiles from measured data **613**
Marian Čerňanský
26.1 Introduction 613
26.2 Preprocessing of data 615
26.3 Methods of restoration 620
26.4 Concluding remarks 644
26.5 References 646

27. Towards higher resolution: a mathematical approach **652**
Derk Reefman
27.1 Introduction to the problem 652
27.2 The instrument function 654
27.3 Deconvolution 657
27.4 Comparison of deconvolution methods 662
27.5 Applications 665
27.6 Conclusions 668
27.7 References 669

Part VII. Applications **671**

28. Use of pattern decomposition to study microstructure: practical aspects and applications **673**
Daniel Louër
28.1 Introduction 673
28.2 The problem of line overlap in powder diffraction 674
28.3 Pattern decomposition 676
28.4 Instrumental correction 680
28.5 Examples 683
28.6 Discussion 694
28.7 References 696

29. X-ray diffraction broadening effects in materials characterization **698**
Giora Kimmel and David Dayan
29.1 Introduction 698
29.2 Techniques and methodology 698
29.3 Metals and alloys 703
29.4 Ceramic materials 717
29.5 Summary and discussion 725
29.6 References 726

30. Crystal size and distortion parameters in fibres using Wide-Angle X-ray Scattering (WAXS) **728**
R. Somashekar
30.1 Introduction 728
30.2 Paracrystallinity 729
30.3 Warren–Averbach method 732
30.4 Single order method 742
30.5 Experimental method for some polymer fibres 745
30.6 Matching of simulated and experimental intensity profiles 751
30.7 Conclusions 752
30.8 References 753

Pressure-induced profile change of energy-dispersive diffraction using synchrotron radiation **755**
Takamitsu Yamanaka
31.1 Introduction 755
31.2 High pressure powder diffraction 757
31.3 Profile change with pressure 760
31.4 Discussion 764
31.5 References 765

x **767**