Table of Contents

Foreword *iii*
Preface *v*
Acknowledgements *vii*

1. INTRODUCTION **1**

1.1. Motivation 1
1.2. Advanced Materials 2
1.3. Thermodynamic Stability 2
1.4. Basis of Nonequilibrium Processing 5
1.5. Some Nonequilibrium Processing Methods 7
1.5.1. Rapid Solidification Processing 7
1.5.2. Mechanical Alloying 7
1.5.3. Plasma Processing 8
1.5.4. Vapor Deposition 8
1.5.5. Spray Forming 8
1.6. Outline of the Book 8
References 9

2. HISTORICAL PERSPECTIVE **11**

2.1. Introduction 11
2.2. Historical Background 11
2.3. Development of High-Energy Ball Milling 12
2.4. Potential of Mechanical Alloying 14
2.5. Potential Resources of Mechanical Alloying Literature 14
References 17

3. NOMENCLATURE 21

3.1. Introduction 21
3.2. Mechanical Alloying 21
3.3. Mechanical Milling/Disordering 22
3.4. Reaction Milling 22
3.5. Cryomilling 23
3.6. Rod Milling 23
3.7. Mechanically Activated Annealing 24
3.8. Double Mechanical Alloying 24
3.9. Mechanically Activated Self-propagating High-temperature Synthesis 24
3.10. Oxidation–Attrition Milling–Reduction 25
3.11. Mechanochemical Processing 26
3.12. Other Methods 26
3.12.1. Repeated Cold Rolling 27
3.12.2. Multilayer Amorphization 28
3.12.3. Severe Plastic Deformation 29
3.12.4. Accumulative Roll Bonding 30
3.13. Acronyms Used in the Literature 32
References 33

4. EQUIPMENT FOR MECHANICAL ALLOYING 35

4.1. Introduction 35
4.2. Raw Materials 36
4.3. Types of Mills 37
4.3.1. Spex Shaker Mills 37
4.3.2. Planetary Ball Mills 39
4.3.3. Attritor Mills 41
4.3.4. Commercial Mills 44
4.3.5. New Designs 47
4.4. Selection of Grinding Medium 55
References 57

5. PROCESS VARIABLES IN MILLING 59

5.1. Introduction 59
5.2. Type of Mill 60
5.3. Milling Container 60
5.4. Milling Energy/Speed 61
5.5. Milling Time 64
5.6. Grinding Medium 64
5.7. Ball-to-Powder Weight Ratio 66
5.8. Extent of Filling the Vial 68
5.9. Milling Atmosphere 69
5.10. Process Control Agents 70
5.10.1. Nature of PCAs 70
5.10.2. Quantity of PCA 72

5.10.3. Constitution of the Milled Powder 74
5.10.4. Choice of PCA 75
5.11. Temperature of Milling 76
References 78

6. MECHANISM OF ALLOYING 83

6.1. Introduction 83
6.2. Ball-Powder-Ball Collisions 83
6.3. Different Stages of Processing 84
6.3.1. Early Stage of Processing 85
6.3.2. Intermediate Stage of Processing 85
6.3.3. Final Stage of Processing 87
6.4. Evolution of Particle Size 87
6.5. Ductile-Ductile Components 89
6.6. Ductile-Brittle Components 91
6.7. Brittle-Brittle Components 92
References 94

7. CHARACTERIZATION OF POWDERS 95

7.1. Introduction 95
7.2. Size and Shape 96
7.3. Surface Area 99
7.4. Phase Constitution 102
7.4.1. Crystalline Phases 102
7.4.2. Quasi-crystalline Phases 104
7.4.3. Amorphous Phases 105
7.5. Microstructural Features 107
7.6. Crystallite Size and Lattice Strain 110
7.7. Transformation Behavior 113
7.8. Grain Growth Studies 117
References 118

8. TEMPERATURE RISE DURING MILLING 121

8.1. Introduction 121
8.2. Types of Temperature Effects 122
8.3. Methods to Evaluate Temperature Rise 123
8.3.1. Methodology Behind the Theoretical Models 123
8.3.2. Theoretical Models 124
8.3.3. Observations Based on Microstructural/Phase Transformations 127
8.3.4. Experimental Observations 128
8.4. Temperature of the Balls 133
8.5. Methods to Minimize Temperature Rise 135
References 136

9. SOLID SOLUBILITY EXTENSIONS **139**

9.1. Introduction 139
9.2. Hume-Rothery Rules for Solid Solution Formation 139
9.3. Formation of Supersaturated Solid Solutions 140
9.4. Measurement of Solid Solubility Limits 142
9.5. Difficulties in Solid Solubility Determination 145
9.6. Effect of Process Variables 156
9.6.1. Milling Temperature 156
9.6.2. Process Control Agent 158
9.6.3. Starting Composition of the Powder Blend 159
9.7. Mechanisms of Solid Solubility Extension 160
9.8. Solid Solubility Plots 164
9.9. Comparison between Mechanical Alloying and Rapid Solidification Processing 169
References 173

10. SYNTHESIS OF INTERMETALLICS **183**

10.1. Introduction 183
10.2. Quasi-crystalline Phases 185
10.2.1. General Features 187
10.2.2. Effect of Process Variables 189
10.3. Crystalline Intermediate Phases 190
10.3.1. Metastable Crystalline Intermediate Phases 191
10.3.2. High-Pressure Phases 193
10.3.3. Equilibrium Crystalline Phases 203
10.4. Role of Hydrogen as a Temporary Alloying Element 207
10.5. Combustion Reactions during MA 209
10.6. Cyclic Phase Transformations 212
10.7. Formation of Ordered Intermetallics 216
10.8. Transformation Behavior of Metastable Intermetallic Phases 217
10.9. Refractory Compounds 220
References 227

11. DISORDERING OF INTERMETALLICS **243**

11.1. Introduction 243
11.2. Methodology 244
11.3. Types of Defects Generated during Disordering and Thermodynamic Stability 245
11.3.1. Antisite Disorder 246
11.3.2. Triple-Defect Disorder 247
11.3.3. Quadruple-Defect Disorder 248
11.3.4. Redistribution of Interstitials 249
11.4. Theoretical Background 251
11.5. Phase Selection 259

11.6. Reordering Kinetics 263
References 264

12. SOLID-STATE AMORPHIZATION 269

12.1. Introduction 269
12.2. Amorphous Phases by MA/MM 270
12.3. Difference between Amorphous Phase Formation by MA and MM 271
12.4. Effect of Process Variables 291
12.4.1. Milling Energy 292
12.4.2. Milling Temperature 293
12.4.3. Powder Contamination 294
12.5. Thermodynamics and Kinetics of Amorphous Phase Formation 295
12.6. Mechanisms and Models for Amorphization 298
12.7. Crystallization Behavior of Amorphous Alloys 304
12.8. Mechanical Crystallization 306
12.9. Bulk Amorphous Alloys 307
12.10. Theoretical Predictions of Amorphous-Phase-Forming Range 312
12.11. Comparison between MA and RSP 315
References 320

13. NANOSTRUCTURED MATERIALS 333

13.1. Introduction 333
13.2. Classification and Characteristics of Nanostructured Materials 333
13.3. Synthesis of Nanostructured Materials 335
13.4. Mechanism of Formation of Nanostructures 337
13.5. Minimal Grain Size 338
13.5.1. Correlation with Material Properties 340
13.5.2. Process Variables 342
13.5.3. Theoretical Estimates 346
13.6. Nanocomposites 346
13.7. Properties of Nanocrystalline Materials 349
13.7.1. Hardness and Strength 349
13.7.2. Ductility 352
13.7.3. Enhanced Sinterability 353
13.7.4. Thermal Stability 353
References 354

14. MECHANOCHEMICAL PROCESSING 359

14.1. Introduction 359
14.2. Thermodynamic Aspects 360

14.3. Process Parameters 369
14.3.1. Milling Temperature 369
14.3.2. Ball-to-Powder Weight Ratio 370
14.3.3. Process Control Agent 371
14.3.4. Relative Proportion of the Reactants 371
14.3.5. Grinding Ball Diameter 372
14.4. Phase Formation 372
14.5. Combustion Reaction 374
14.6. Reaction Mechanisms 375
14.6.1. Thermal Theories 375
14.6.2. Reactions Induced by Shear 376
14.6.3. Theory of Surface Active States 376
14.7. Mechanosynthesis of Ceramics and Nanocomposites 377
References 379

15. POWDER CONTAMINATION 385

15.1. Introduction 385
15.2. Sources of Contamination 386
15.2.1. Starting Powders 387
15.2.2. Milling Atmosphere 392
15.2.3. Milling Equipment 393
15.3. Elimination/Minimization of Contamination 395
15.3.1. Milling Equipment 396
15.3.2. Milling Atmosphere 398
15.3.3. Process Control Agent 400
References 402

16. MODELING STUDIES AND MILLING MAPS 405

16.1. Introduction 405
16.2. Process Variables 405
16.3. Early Modeling Attempts 406
16.4. Types of Modeling 407
16.4.1. Local Modeling 407
16.4.2. Global Modeling 411
16.5. Milling Maps 413
References 416

17. APPLICATIONS 419

17.1. Introduction 419
17.2. Oxide Dispersion Strengthened Materials 420
17.2.1. ODS Nickel-Based Alloys 421
17.2.2. ODS Iron-Based Alloys 424
17.2.3. ODS Aluminum-Based Alloys 425

17.3. Magnesium-Based Alloys 429
17.3.1. Supercorroding Alloys 429
17.3.2. Hydrogen Storage Materials 429
17.4. Other Applications 434
17.4.1. Spray Coatings 434
17.4.2. Thermoelectric Power Generator Materials 435
17.4.3. Waste Utilization 436
17.4.4. Metal Extraction 438
17.4.5. Processing of Polymers 439
17.4.6. Room Temperature Solders 441
17.4.7. Biomaterials 441
17.4.8. Bearings 442
17.4.9. Miscellaneous Applications 443
17.5. Concluding Remarks 443
References 444

18. SAFETY HAZARDS 447

18.1. Introduction 447
18.2. Hazards Related to Mechanical Alloying Processes 448
18.2.1. Heat Evolution 448
18.2.2. Gas Evolution 449
18.2.3. Explosions 449
18.3. Handling of Mechanically Alloyed Powders 449
18.4. Accident Avoidance 450
References 451

19. CONCLUDING REMARKS 453

Index *457*