

CONTENTS

1.	INTRODUCTION	1
1.1.	Background	1
1.2.	Objective	2
1.3.	Scope	2
1.4.	Structure..	2
2.	REVIEW OF ACCIDENTS	3
2.1.	Definitions	3
2.2.	Methodology for the review	5
2.3.	Clinical considerations related to quality assurance	6
2.4.	Radiation measurement systems	7
2.5.	External beam therapy: Machine commissioning and calibration	10
2.6.	External beam therapy: Treatment planning, patient setup and treatment	22
2.7.	Decommissioning of teletherapy equipment	36
2.8.	Mechanical and electrical malfunctions	39
2.9.	Brachytherapy: Low dose rate sources and applicators	40
2.10.	Brachytherapy (high dose rate)	59
2.11.	Unsealed sources	61
3.	CLASSIFICATION OF ACCIDENTS	66
3.1.	Classification of causes based on radiotherapy techniques	66
3.2.	External beam therapy	67
3.3.	Low dose rate brachytherapy	69
3.4.	High dose rate brachytherapy	70
3.5.	Use of unsealed sources	70
4.	LESSONS LEARNED AND MEASURES FOR PREVENTION OF ACCIDENTS	71
4.1.	Resources: Personnel and equipment	71
4.2.	Human factors	71
4.3.	Training	73

4.4. Communication	74
4.5. Equipment	75
4.6. Human-machine problems	78
4.7. Improper decommissioning of equipment and unsafe storage of radioactive sources	79
4.8. Documentation	80
4.9. Integration of safety and quality assurance	81
4.10. Safety assessment	82
4.11. Regulatory control	86

APPENDIX: APPENDIX II OF THE BSS — MEDICAL EXPOSURE: OPTIMIZATION OF PROTECTION FOR MEDICAL EXPOSURES	87
REFERENCES	90
CONTRIBUTORS TO DRAFTING AND REVIEW	91
RELATED IAEA PUBLICATIONS	93