

# CONTENTS

1.	INTRODUCTION . . . .I.....	1
1.1.	Background . . . . .	11
1.2.	Advantages of a Code of Practice based on standards of absorbed dose to water . . . . .	5
1.2.1.	Reduced uncertainty . . . . .	5
1.2.2.	A more robust system of primary standards . . . . .	6
1.2.3.	Use of a simple formalism . . . . .	7
1.3.	Types of radiation and range of beam qualities . . . . .	7
1.4.	Practical use of this Code of Practice . . . . .	8
1.5.	Expression of uncertainties . . . . .	9
1.6.	Quantities and symbols . . . . .	9
1.7.	Abbreviations of organizations . . . . .	14
2.	FRAMEWORK . . . . .	15
2.1.	The International Measurement System . . . . .	15
2.1.1.	The IAEA/WHO network of SSDLs . . . . .	16
2.2.	Standards of absorbed dose to water . . . . .	17
3.	$N_{D,w}$ BASED FORMALISM . . . . .	21
3.1.	Formalism . . . . .	21
3.1.1.	Reference conditions . . . . .	21
3.1.2.	Influence quantities . . . . .	22
3.2.	Correction for the radiation quality of the beam, $k_{Q,Q_0}$ . . . . .	22
3.2.1.	A modified $k_{Q,Q_0}$ for electron beam cross-calibrations . . . . .	24
3.3.	Relation to $N_K$ based codes of practice . . . . .	26
4.	IMPLEMENTATION . . . . .	27
4.1.	General . . . . .	27
4.2.	Equipment . . . . .	29
4.2.1.	Ionization chambers . . . . .	30
4.2.2.	Measuring assembly . . . . .	38
4.2.3.	Phantoms . . . . .	39
4.2.4.	Waterproof sleeve for the chamber . . . . .	41
4.2.5.	Positioning of ionization chambers at the reference depth . . . . .	41

4.3.	Calibration of ionization chambers	44
4.3.1.	Calibration in a $^{60}\text{Co}$ beam	44
4.3.2.	Calibration in kilovoltage X rays	46
4.3.3.	Calibration at other qualities	46
4.4.	Reference dosimetry in the user beam	48
4.4.1.	Determination of the absorbed dose to water	48
4.4.2.	Practical considerations for measurements in the user beam	48
4.4.3.	Correction for influence quantities	49
5.	CODE OF PRACTICE FOR $^{60}\text{Co}$ GAMMA RAY BEAMS . . . . . I.	57
5.1.	General	57
5.2.	Dosimetry equipment	57
5.2.1.	Ionization chambers	57
5.2.2.	Phantoms and chamber sleeves	57
5.3.	Beam quality specification	58
5.4.	Determination of absorbed dose to water	58
5.4.1.	Reference conditions	58
5.4.2.	Determination of absorbed dose under reference conditions	59
5.4.3.	Absorbed dose at $z_{\text{max}}$	60
5.5.	Cross-calibration of field ionization chambers	60
5.6.	Measurements under non-reference conditions	60
5.6.1.	Central axis depth dose distributions	61
5.6.2.	Output factors	61
5.7.	Estimated uncertainty in the determination of absorbed dose to water under reference conditions	62
5.8.	Worksheet	64
6.	CODE OF PRACTICE FOR HIGH ENERGY PHOTON BEAMS . . . . .	66
6.1.	General	66
6.2.	Dosimetry equipment	66
6.2.1.	Ionization chambers	66
6.2.2.	Phantoms and chamber sleeves	67
6.3.	Beam quality specification	68
6.3.1.	Choice of beam quality index	68
6.3.2.	Measurement of beam quality	69
6.4.	Determination of absorbed dose to water	70

6.4.1.	Reference conditions	70
6.4.2.	Determination of absorbed dose under reference conditions	70
6.4.3.	Absorbed dose at $z_{\max}$	71
6.5.	Values for $k_{Q,Q_0}$	75
6.5.1.	Chamber calibrated in $^{60}\text{Co}$	75
6.5.2.	Chamber calibrated in a series of photon beam qualities	75
6.5.3.	Chamber calibrated at $Q_0$ with generic experimental $k_{Q,Q_0}$ values	77
6.6.	Cross-calibration of field ionization chambers	77
6.7.	Measurements under non-reference conditions	78
6.7.1.	Central axis depth dose distributions	78
6.7.2.	Output factors	79
6.8.	Estimated uncertainty in the determination of absorbed dose to water under reference conditions	79
6.9.	Worksheet	81

## 7. CODE OF PRACTICE FOR HIGH-ENERGY ELECTRON BEAMS . . . 84

7.1.	General	84
7.2.	Dosimetry equipment	84
7.2.1.	Ionization chambers	84
7.2.2.	Phantoms and chamber sleeves	85
7.3.	Beam quality specification	86
7.3.1.	Choice of beam quality index	86
7.3.2.	Measurement of beam quality	86
7.4.	Determination of absorbed dose to water	88
7.4.1.	Reference conditions	88
7.4.2.	Determination of absorbed dose under reference conditions	89
7.4.3.	Absorbed dose at $z_{\max}$	90
7.5.	Values for $k_{Q,Q_0}$	90
7.5.1.	Chamber calibrated in $^{60}\text{Co}$	90
7.5.2.	Chamber calibrated at a series of electron beam qualities	90
7.6.	Cross-calibration of ionization chambers	94
7.6.1.	Cross-calibration procedure	94
7.6.2.	Subsequent use of a cross-calibrated chamber	95
7.7.	Measurements under non-reference conditions	98
7.7.1.	Central axis depth dose distributions	98

7.7.2.	Output factors	101
7.8.	Use of plastic phantoms	101
7.8.1.	Scaling of depths	102
7.8.2.	Plastic phantoms for beam quality specification	102
7.8.3.	Plastic phantoms for absorbed dose determination at $z_{\text{ref}}$	103
7.8.4.	Plastic phantoms for depth dose distributions	103
7.9.	Estimated uncertainty in the determination of absorbed dose to water under reference conditions	104
7.10.	Worksheet	107
<b>8.</b>	<b>CODE OF PRACTICE FOR LOW ENERGY KILOVOLTAGE X RAY BEAMS</b>	<b>110</b>
8.1.	General	110
<b>8.2.</b>	<b>Dosimetry equipment</b>	<b>111</b>
8.2.1.	Ionization chambers	111
8.2.2.	Phantoms	112
<b>8.3.</b>	<b>Beam quality specification</b>	<b>112</b>
8.3.1.	Choice of beam quality index	112
8.3.2.	Measurement of beam quality	114
<b>8.4.</b>	<b>Determination of absorbed dose to water</b>	<b>115</b>
8.4.1.	Reference conditions	115
8.4.2.	Determination of absorbed dose under reference conditions	115
<b>8.5.</b>	<b>Values for <math>k_{Q,0}</math></b>	<b>116</b>
<b>8.6.</b>	<b>Measurements under non-reference conditions</b>	<b>117</b>
8.6.1.	Central axis depth dose distributions	117
8.6.2.	Output factors	117
<b>8.7.</b>	<b>Estimated uncertainty in the determination of absorbed dose to water under reference conditions</b>	<b>118</b>
<b>8.8.</b>	<b>Worksheet</b>	<b>120</b>
<b>9.</b>	<b>CODE OF PRACTICE FOR MEDIUM ENERGY KILOVOLTAGE X RAY BEAMS</b>	<b>122</b>
9.1.	General	122
9.2.	Dosimetry equipment	123
9.2.1.	Ionization chambers	123
9.2.2.	Phantoms and chamber sleeves	124
9.3.	Beam quality specification	125
9.3.1.	Choice of beam quality index	125

9.3.2.	Measurement of beam quality .....	126
9.4.	Determination of absorbed dose to water .....	127
9.4.1.	Reference conditions .....	127
9.4.2.	Determination of absorbed dose under reference conditions .....	127
9.5.	Values for $k_{Q,Q_0}$ .....	127
9.6.	Measurements under non-reference conditions .....	129
9.6.1.	Central axis depth dose distributions .....	129
9.6.2.	Output factors .....	131
9.7.	Estimated uncertainty in the determination of absorbed dose to water under reference conditions .....	131
9.8.	Worksheet .....	133
10.	CODE OF PRACTICE FOR PROTON BEAMS .....	135
10.1.	General .....	135
10.2.	Dosimetry equipment .....	137
10.2.1.	Ionization chambers .....	137
10.2.2.	Phantoms and chamber sleeves .....	137
10.3.	Beam quality specification .....	138
10.3.1.	Choice of beam quality index .....	138
10.3.2.	Measurement of beam quality .....	139
10.4.	Determination of absorbed dose to water .....	140
10.4.1.	Reference conditions .....	140
10.4.2.	Determination of absorbed dose under reference conditions .....	141
10.5.	Values for $k_{Q,Q_0}$ .....	141
10.6.	Measurements under non-reference conditions .....	141
10.6.1.	Central axis depth dose distributions .....	145
10.6.2.	Output factors .....	146
10.6.3.	Use of plastic phantoms for relative dosimetry .....	146
10.7.	Estimated uncertainty in the determination of absorbed dose to water under reference conditions .....	148
10.8.	Worksheet .....	149
11.	CODE OF PRACTICE FOR HEAVY ION BEAMS .....	151
11.1.	General .....	151
11.2.	Dosimetry equipment .....	154
11.2.1.	Ionization chambers .....	154
11.2.2.	Phantoms and chamber sleeves .....	155

11.3. Beam quality specification	156
11.4. Determination of absorbed dose to water	156
11.4.1. Reference conditions	156
11.4.2. Determination of absorbed dose under reference conditions	157
11.5. Values for $k_{Q_0}$	157
11.6. Measurements under non-reference conditions	158
11.7. Estimated uncertainty in the determination of absorbed dose to water under reference conditions	160
11.8. Worksheet	162

APPENDIX I. RELATION BETWEEN  $N_K$  AND  $N_{D,w}$  BASED  
CODES OF PRACTICE 165

I.1. $^{60}\text{Co}$ and high energy photon and electron beams	165
I.1.1. A summary of notations used for calibration factors	169
I.1.2. Comparison of $D_w$ determinations	169
I.2. Kilovoltage X ray beams	172

APPENDIX II. CALCULATION OF  $k_{Q_0}$  AND ITS UNCERTAINTY 174

II. 1. General	174
11.2. $^{60}\text{Co}$ gamma radiation	175
11.2.1. Value for $s_{w,air}$ in $^{60}\text{Co}$	175
11.2.2. Value for $W_{air}$ in $^{60}\text{Co}$	175
11.2.3. Values for $p_Q$ in $^{60}\text{Co}$	175
11.2.4. Summary of values and uncertainties in $^{60}\text{Co}$	178
11.3. High energy photon beams	178
11.3.1. Values for $s_{w,air}$ in high energy photon beams	178
11.3.2. Value for $W_{air}$ in high energy photon beams	178
11.3.3. Values for $p_Q$ in high energy photon beams	181
11.3.4. Summary of uncertainties in high energy photon beams	183
11.4. Electron beams	185
11.4.1. Values for $s_{w,air}$ in electron beams	185
11.4.2. Value for $W_{air}$ in electron beams	186
11.4.3. Values for $p_Q$ in electron beams	186
11.4.4. Summary of uncertainties in electron beams	189
11.5. Proton beams	190
11.5.1. Values for $s_{w,air}$ in proton beams	190
11.5.2. Value for $W_{air}$ in proton beams	192
11.5.3. Values for $p_Q$ in proton beams	192

II.5.4.	Summary of uncertainties in proton beams	193
II.6.	Heavy ion beams	194
II.6.1.	Value for $s_{w,air}$ in heavy ion beams	194
II.6.2.	Value for $W_{air}$ in heavy ion beams	196
II.6.3.	Value for $p_Q$ in heavy ion beams	196
II.6.4.	Summary of uncertainties in heavy ion beams	196
APPENDIX III. PHOTON BEAM QUALITY SPECIFICATION		198
III.1.	Overview of common photon beam quality specifiers	198
III.2.	Advantages and disadvantages of $TPR_{20,10}$	200
III.3.	Advantages and disadvantages of $PDD(10)_x$	203
III.4.	Concluding remarks	208
APPENDIX IV. EXPRESSION OF UNCERTAINTIES		210
IV. 1.	General considerations on errors and uncertainties	210
IV.2.	Type A standard uncertainties	2 11
IV.3.	Type B standard uncertainties	2 12
IV.4.	Combined and expanded uncertainties	213
REFERENCES		215
CONTRIBUTORS TO DRAFTING AND REVIEW		226
RELATED IAEA PUBLICATIONS		229