Contents

Preface vii Dedication ix Introduction xi

- 1. The melt 1
 - 1.1 Reactions of the melt with its environment 2
 - Transport of gases in melts 10 1.2
 - Surface film formation 12 1.3
- 2. Entrainment 17
 - Entrainment defects 20 2.1
 - 2.2
 - Entrainment processes 31 Furling and unfurling 54 2.3
 - 2.4 Deactivation of entrained films 61
 - 2.5 Soluble, transient films 63
 - 2.6 Detrainment 64
 - 2.7 Evidence for bifilms 64
 - 2.8 The significance of bifilms 67
- 3. Flow 70
 - Effect of surface films on filling 70 3.1
 - 3.2 Effect of entrained films on filling 73
 - Fluidity (maximum fluidity length) Lf 74 3.3
 - 3.4
 - Continuous fluidity 95 Glossary of symbols 98 3.5

4. The mould 99

- 4.1 Inert moulds 99
- Aggregate moulds 100 4.2
- Mould atmosphere 105 4.3
- Mould surface reactions 111 4.4
- 4.5 Metal surface reactions 114
- 5. Solidification structure 117
 - Heat transfer 117 5.1
 - 5.2 Development of matrix structure 129
 - 5.3 Segregation 139
 - 5.4 Aluminium alloys 147
 - 5.5 Cast irons 156 Steels 167 5.6
- 6. Gas porosity 178 6.1 Nucleation of gas porosity 178

- Subsurface porosity 186 Growth of gas pores 195 Blowholes 200 6.2
- 6.3 6.4
- 7. Solidification shrinkage 205
 - 7.1 General shrinkage behaviour 205
 - Solidification shrinkage 206 7.2
 - 7.3 Feeding criteria 210
 - 7.4 Feeding - the five mechanisms 212
 - 7.5 Initiation of shrinkage porosity 222
 - Growth of shrinkage pores 226 7.6
 - 7.7 Final forms of shrinkage porosity 227
- 8. Linear contraction 232
 - Uniform contraction 232 8.1
 - Non-uniform contraction (distortion) 237 8.2
 - 8.3 Hot tearing 242
 - 8.4
 - Cold cracking 258 Residual stress 259 8.5
- 9. Structure, defects and properties of the finished casting 267 9.1 Grain size 267

 - 9.2 Dendrite arm spacing 270
 - 9.3 Compact defects 275
 - Planar defects 279 9.4
 - 9.5 Effects of defects on properties of castings 282
 - 9.6 The statistics of failure 301
- 10. Processing 306
 - 10.1 Impregnation 306
 - 10.2
 - Hot isostatic pressing 306 Working (forging, rolling and 10.3
 - extrusion) 309
 - 10.4 Machining 309 10.5 Painting 310
- 11. Environmental interactions 311 11.1 Internal oxidation 311 11.2 Corrosion 313

Postscript 318 References 320 Index 331