

Table of Contents

1. Properties of X-Rays	1
2. Geometry of Crystals	31
3. Diffraction I: Geometry	91
4. Diffraction II: Intensities of Diffracted Beams	125
5. Diffraction III: Real Samples	171
6. Diffraction Measurements	191
7. Powder Photographs	243
8. Laue Photographs	271
9. Phase Identification by X-Ray Diffraction	283
10. Determination of Crystal Structure	305
11. Phase-Diagram Determination	343
12. Quantitative Phase Analysis	359
13. Precise Parameter Measurements	375

14. Structure of Polycrystalline Aggregates	399
15. Stress Measurement	451
16. Orientation of Single Crystals	487
17. Crystal Quality	519
18. Polymers	557
19. Small Angle Scattering	573
20. Transmission Electron Microscopy	589
Appendix: Electron and Neutron Diffraction	611
Appendix: Lattice Geometry	615
Appendix: The Rhombohedral-Hexagonal Transformation	619
Appendix: X-Ray Wavelengths	623
Appendix: Quadratic Forms of Miller Indices	627
Appendix: Atomic Scattering Factors	629
Appendix: Multiplicity Factors for the Powder Method	633
Appendix: Lorentz-Polarization Factor	635
Appendix: Data for Calculation of the Temperature Factor	639
Index	641