

CONTENTS

Preface	ix
Acknowledgements	x
Introduction	xi
1. The Pelton Turbine	1
1.1 Why Pelton turbines?	1
1.2 General description of a Pelton turbine	2
1.3 The origins of the Pelton wheel	5
1.3.1 Early water mills	5
1.3.2 Tangential wheels	6
1.3.3 The Pelton wheel	8
2. Basic Theory	11
2.1 Impulse and reaction turbines	11
2.2 Water jets	11
2.2.1 Nozzles	11
2.2.2 Spear valves	12
2.2.3 Jets	12
2.3 Buckets and the runner	15
2.3.1 Simple theory	15
2.3.2 Flow into the buckets	15
2.3.3 A more complete theory	17
2.3.4 Windage and mechanical friction losses	18
2.3.5 Overall efficiency	19
2.3.6 Optimum speed	21
2.3.7 Runaway speed	22
2.4 Casing design and multiple jets	22
3. Turbine Selection	24
3.1 Pelton turbine selection	24
3.1.1 Flow equation	24
3.1.2 Speed equation	26
3.1.3 Power equation	26
3.1.4 General procedure	27
3.1.5 Worked example	27
3.1.6 Making a final choice	27
3.1.7 Further examples	29
4. Design	32
4.1 The buckets	32
4.1.1 Bucket shape	32
4.1.2 A bucket design	33
4.1.3 Bucket materials	34
4.1.4 Stress calculations	37
4.2 The runner	39
4.2.1 The number of buckets	39
4.2.2 Attaching the bucket to the hub	39
4.3 Spear valves and nozzles	44
4.3.1 Nozzles or spear valves?	44
4.3.2 Nozzles	45

4.3.3	Spear valves	46
4.3.4	The number of jets and jet spacing	50
4.3.5	The effect of the nozzles or spear valves on the penstock	51
4.4	Overspeed protection: deflectors and other mechanisms	52
4.4.1	The need for overspeed protection	52
4.4.2	Deflectors	52
4.4.3	Other shut-down mechanisms	54
4.4.4	Overspeed sensing	55
4.5	General shaft and bearing layout	55
4.5.1	Direct shaft mounting	55
4.5.2	'Peltric' sets	56
4.5.3	Separately mounted runners	56
4.6	Shaft and bearing forces	58
4.7	Runner shaft bearings	60
4.7.1	General considerations	60
4.7.2	Bearing arrangement	61
4.7.3	Selecting the correct bearing size	63
4.7.4	Tolerancing of mating components	64
4.7.5	Bearing lubrication and sealing	65
4.8	Shafts	67
4.8.1	Shaft design	67
4.8.2	Shaft stress	67
4.8.3	Attaching the runner to the shaft	68
4.8.4	Corrosion protection	71
4.9	Turbine shaft seals	72
4.10	Manifolds	73
4.10.1	Determining the size of the manifold	73
4.10.2	Manifold losses	74
4.10.3	Manifold stresses	74
4.11	Shut-off valves	76
4.11.1	Gate valves	77
4.11.2	Butterfly valves	77
4.11.3	Ball valves	77
4.12	Turbine housing	78
4.12.1	Controlling flow within the casing	78
4.12.2	Casing construction	80
4.12.3	Open turbines	81
4.13	Baseframes, foundations and tailrace	81
4.13.1	Baseframes	81
4.13.2	Foundations, floors and anchor bolts	83
4.13.3	Tailrace	85
4.14	Associated components	87
4.14.1	Desilting basin	87
4.14.2	Trashrack	87
4.14.3	Generators	87
4.14.4	Governors, load controllers and flywheels	87
5. Manufacture		91
5.1	Buckets	91
5.1.1	Pattern making	91
5.1.2	Casting single buckets	96
5.1.3	Casting runners in one piece	105
5.1.4	Balancing	110
5.2	Fabricated runners	111
5.2.1	Bolted assemblies	111
5.2.2	Welded assemblies	113
5.2.3	Testing	114

5.2.4	Other methods of manufacturing runners	115
5.3	Spear valves	116
5.4	Manifolds	116
5.5	Turbine housing	116
5.6	Assembly	117
5.6.1	General bearing assembly	117
5.6.2	Fitting taper-sleeve bearings to the shaft	119
5.7	Packing and transport	120
6. Installation, Commissioning and Testing		121
6.1	Installation	121
6.2	Commissioning	121
6.2.1	Commissioning procedure	121
7. Maintenance and Problem Solving		123
7.1	Maintenance	123
7.1.1	Regular inspection	123
7.1.2	Bearings	123
7.1.3	Major inspection	124
7.2	Problem solving	124
7.2.1	Low output power	124
7.2.2	Noise and vibration	128
7.2.3	Leaks	128
8. Conclusion		129
8.1	Further developments	129
9. Appendix: Standard Units, Formulae and Notation		130
9.1	Standard units	130
9.2	Multiplication factors	130
9.3	Other SI units	130
9.4	Basic formulae	130
9.4.1	Turbine output power	130
9.4.2	Power/torque relationship	131
9.5	Unit conversion	131
9.6	Greek alphabet	132
9.7	Accuracy and the acceleration due to gravity	132
10. Appendix: Derivation of Formulae		133
10.1	Nozzles	133
10.2	Spear valves	134
10.3	Turbine power and efficiency	136
10.3.1	Simple theory	136
10.3.2	Water missing the runner	137
10.3.3	Three-dimensional theory	140
10.3.4	Windage losses	142
10.3.5	Mechanical friction losses	143
10.4	Bucket stem stress calculations	143
10.4.1	Runaway load	144
10.4.2	Fatigue load	145
10.4.3	Stress limits	146
10.5	Bolted buckets	148
10.5.1	Standard analysis	148

10.5.2 Analysis of a bolted bucket	148
10.6 Shaft design	149
10.6.1 Static loads	149
10.6.2 Fatigue loads	150
10.7 Manifold loss calculations	151
10.7.1 Pipe losses	151
10.7.2 Bend losses	152
10.7.3 Bifurcation losses	153
10.7.4 Diameter transition losses	154
10.7.5 Worked example	154
10.8 Baseframe anchor bolt loads	157
11. Appendix: Full System Calculation Spreadsheet	158
11.1 Using the spreadsheets	158
11.1.1 Part 1. Penstock losses, turbine jet size and speed calculations	158
11.1.2 Part 2. Power calculations	161
11.1.3 Part 3. Penstock thickness calculations	161
12. Appendix: O-ring seals	163
12.1 Sealing arrangements	163
12.2 O-ring section and groove details	163
12.3 O-ring diameter	165
12.4 Material	165
12.5 Installation	165
13. Appendix: Keys and Keyways	166
14. Appendix: Limits and Fits	168
14.1 Selected fits	168
15. Appendix: Specific Speeds	172
15.1 Definition of specific speed	172
15.2 Choosing a turbine	172
16. References	174
17. Glossary	176
18. Index	177