

CONTENTS

<i>Preface</i>	<i>xiii</i>
<i>About the Author</i>	<i>xv</i>
1. The General Idea	1
1.1 Concepts	1
1.2 How Does Drawing Work?	2
1.3 Questions and Problems	6
2. A Brief History of Technology	7
2.1 Ancient and Early Technology	7
2.2 The Nineteenth Century	9
2.3 The Twentieth Century	10
2.4 Further Reading	11
2.5 Questions and Problems	11
3. Twentieth Century Equipment Concepts	13
3.1 Overview	13
3.2 Benches	13
3.3 Blocks	14
3.4 Multiple-Die Machines	15
3.5 Other In-Line Processes	17
3.6 Post-Twentieth Century Developments	17
3.7 Questions and Problems	18
4. Basic Engineering Variables Pertinent to Drawing	19
4.1 General Quantities	19
4.2 Quantities Describing the Workpiece and Die During Drawing	23
4.3 Questions and Problems	27
5. Basic Drawing Mechanics	29
5.1 A Simple Drawing Stress Model	29
5.2 Drawing Limits	34
5.3 An Illustrative Calculation	34
5.4 The Issue of Optimum Die Angles and Δ Values	34
5.5 Die Pressure	35
5.6 Centerline Tension	37

5.7	Plastic Flow Outside the Drawing Cone	39
5.8	Effects of Back Tension	40
5.9	Systems of Analysis	41
5.10	Questions and Problems	41
6.	Drawing Temperature	45
6.1	Contributions to the Drawing Temperature	45
6.2	Temperature Measurement	50
6.3	Interpass Cooling	52
6.4	Practical Examples of Drawing Temperature Effects	52
6.5	Questions and Problems	58
7.	Drawing Speed	59
7.1	Definition and Basic Formulas	59
7.2	The Role of Drawing Speed in Analysis	60
7.3	The Effect of Drawing Speed on Lubrication	62
7.4	Some Practical Issues	63
7.5	Questions and Problems	64
8.	Friction, Lubrication, and Surface Quality	67
8.1	Modes of Lubrication and Related Friction Response	67
8.2	Physical Conditions in the Lubricant Layer	73
8.3	Quantifying the Friction Stress	76
8.4	Drawing with High Friction	77
8.5	Redraw Stock Surface Conditioning Issues	78
8.6	Characterization with Microscopy	79
8.7	Illustrations of Microscopic Characterization and Analysis	80
8.8	The Development of Chevrons (Crow's Feet)	84
8.9	Questions and Problems	89
9.	Drawing Die and Pass Schedule Design	91
9.1	General Aspects and the Role of Δ	92
9.2	Common Die Materials	96
9.3	Other Elements of Die Design	100
9.4	Pressure Dies	103
9.5	Die Wear and Die Life	105
9.6	Pass Schedule Concepts	107
9.7	Drawing Practice and Cast and Pitch Control	111
9.8	Questions and Problems	113

10.	Shaped Dies and Roller Dies	115
10.1	Drawing Shapes with One-Piece Dies	115
10.2	Drawing with Unpowered Roller Die Systems	120
10.3	"Drawing" with Powered Roller Die Systems	123
10.4	Roll Gap Issues	125
10.5	Questions and Problems	126
11.	Mechanical Properties of Wire and Related Testing	129
11.1	The Flow Stress of the Wire	130
11.2	The Tensile Test	132
11.3	The Crystal Plasticity Basis for the Flow Curve	140
11.4	Other Mechanical Tests	146
11.5	Hardness Tests	146
11.6	Compression Tests	148
11.7	Bending Tests	150
11.8	Torsion Tests	152
11.9	Creep Testing	153
11.10	Fatigue Testing	154
11.11	Springback Testing	155
11.12	Evaluating Residual Stress	156
11.13	Questions and Problems	157
12.	Drawability and Breaks	159
12.1	Practical Definitions	159
12.2	Measuring and Estimating Drawability	160
12.3	Categorizing Drawing Breaks	166
12.4	Mechanics of Drawing Breaks	168
12.5	The Generation of "Fines"	173
12.6	Questions and Problems	175
13.	Relevant Aspects of Copper and Copper Alloy Metallurgy	177
13.1	Important Properties of Copper	178
13.2	Primary Processing	178
13.3	Crystal Structure, Grains, Texture, Anisotropy, and Springback	181
13.4	Flow Stress, Cold Working, and Annealing	184
13.5	Solid Solutions and Phases	188
13.6	Factors Affecting Conductivity/Resistivity	190
13.7	Dilute Copper Alloys	192
13.8	High-Alloy Systems	194

13.9	Beryllium Copper, a Precipitation Strengthening (Hardening) Alloy	198
13.10	Questions and Problems	199
14.	Relevant Aspects of Carbon and Low-Alloy Steel Metallurgy	201
14.1	Important Properties of Steel	202
14.2	Primary Processing	202
14.3	The Iron-Iron Carbide Phase Diagram	205
14.4	Austenite Decomposition	209
14.5	Structure-Mechanical Property Relations	212
14.6	Transformation Diagrams	212
14.7	Flow Stress, Cold Working, and Annealing	217
14.8	Aging in Steel	220
14.9	Carbon Steel Compositions	227
14.10	Low-Alloy Steel Compositions	228
14.11	Recent Technology and Literature	229
14.12	Questions and Problems	232
15.	Other Metallurgical Systems for Wire Technology	235
15.1	Aluminum and its Alloys	235
15.2	Austenitic Stainless Steels	240
15.3	Tool Steels	243
15.4	Nickel and Nickel Alloys	246
15.5	Questions and Problems	249
16.	Wire Coatings	251
16.1	Reasons for Coating Wire	251
16.2	Coating Types and Coating Processes	252
16.3	Enamels and Enameling	252
16.4	Extrusion	253
16.5	Hot Dipping	255
16.6	Electrocoating	256
16.7	Other Coating Technologies	257
16.8	Zinc Alloy Coating of Steel—A Detailed Illustration and Analysis	257
16.9	Composite Mechanical Properties of Coated Wire	259
16.10	Questions and Problems	262
17.	Redraw Rod Production	263
17.1	The Rod Rolling Process	263
17.2	The Oval/Round Sequence	265
17.3	Other Geometrical Sequences	269

17.4	Some Process Correction Contexts	270
17.5	Questions and Problems	271
18.	Wire Forming	273
18.1	Scope	273
18.2	Bending	273
18.3	Twisting	275
18.4	Stretching	277
18.5	Upsetting	277
18.6	Swaging	277
18.7	Cold Extrusion	282
18.8	Questions and Problems	284
19.	Physical Properties	285
19.1	Scope	285
19.2	Density	285
19.3	Melting Points and Ranges	286
19.4	Specific Heat	287
19.5	Thermal Conductivity	287
19.6	Electrical Resistivity	288
20.	Current and Near-Term Developments	289
20.1	Scope	289
20.2	Drawing Machines	290
20.3	Metallurgical Powders for High-Wear-Resistance Wire Dies	291
20.4	Fully Synthetic Lubricant for Copper Wire Drawing	292
20.5	Wire Guides	292
20.6	Annealing	292
20.7	Diameter Measurements	293
20.8	Temperature Measurements	295
	<i>References</i>	297
	<i>List of Symbols</i>	305
	<i>Selected Formulae</i>	311
	<i>Index</i>	315