

# Contents

<b>1</b>	<b>Introduction</b> . . . . .	<b>1</b>
<b>2</b>	<b>Types of Differential Scanning Calorimeters</b> . . . . .	<b>7</b>
2.1	The Heat Flux DSC . . . . .	8
2.1.1	Heat Flux DSC with a Disk-Type Measuring System . . . . .	8
2.1.2	Heat Flux DSC with a Cylinder-Type Measuring System . . . . .	11
2.2	The Power Compensation DSC . . . . .	14
<b>3</b>	<b>Theoretical Fundamentals of Differential Scanning Calorimeters</b> . . . . .	<b>21</b>
3.1	The Heat Flux DSC . . . . .	21
3.2	The Power Compensation DSC . . . . .	38
<b>4</b>	<b>Calibration of Differential Scanning Calorimeters</b> . . . . .	<b>41</b>
4.1	Aspects of Quality Assurance . . . . .	41
4.2	Thermodynamic Aspects . . . . .	42
4.3	Temperature Calibration . . . . .	43
4.3.1	Calibration Procedure . . . . .	45
4.3.2	Arguments in Support of the Temperature Calibration Procedure . . . . .	52
4.3.3	Examples of Temperature Calibration . . . . .	54
4.4	Caloric Calibration . . . . .	61
4.4.1	Heat Flow Rate Calibration . . . . .	62
4.4.2	Peak Area Calibration . . . . .	65
4.4.3	Examples of Caloric Calibrations . . . . .	68
4.5	Conclusions Regarding the Calibration of DSCs . . . . .	72
4.6	Calibration Substances . . . . .	73
4.6.1	Calibration Substances for Temperature Calibration . . . . .	74
4.6.2	Calibration Substances for Heat Flow Rate Calibration . . . . .	75
4.6.3	Calibration Substances for Peak Area Calibration . . . . .	76

5	<b>The DSC Curve . . . . .</b>	<b>81</b>
5.1	Characteristic Terms . . . . .	82
5.2	Influencing Parameters . . . . .	83
5.3	The Baseline and the Determination of the Thermodynamic Functions . . . . .	84
5.4	Desmearing of the DSC Curve . . . . .	89
5.4.1	Correction of the Temperature and Heat Flow Rate Indicated . . . . .	91
5.4.2	Subtraction of the Baseline . . . . .	92
5.4.3	Calculation of the True Flow Rate into the Sample . . . . .	92
5.4.4	Advanced Desmearing . . . . .	96
5.4.5	Further Calculations . . . . .	102
5.5	Interpretation and Presentation . . . . .	103
6	<b>Applications of Differential Scanning Calorimetry . . . . .</b>	<b>105</b>
6.1	General Applications Without Sophisticated Evaluation of the Measured Curve . . . . .	105
6.1.1	Identification of Substances, the Phase Behavior . . . . .	105
6.1.2	Determination of Phase Diagrams . . . . .	111
6.1.3	Safety Aspects . . . . .	113
6.1.4	Characterization of Polymers by Thermal Analysis; Effects of Origin and Thermal History . . . . .	114
6.1.5	Determination of the Degree of Crystallinity . . . . .	115
6.2	Applications Requiring a Detailed Evaluation of the Measured Curve . . . . .	118
6.2.1	Measurements of the Heat Capacity . . . . .	118
6.2.1.1	The "Classical" Three Step Procedure . . . . .	119
6.2.1.2	The "Absolute" Dual Step Method . . . . .	124
6.2.1.3	A Variation of the Classical Technique . . . . .	124
6.2.1.4	A Discontinuous Procedure . . . . .	127
6.2.1.5	Determination Using the Dual DSC . . . . .	129
6.2.1.6	General Precautions for the Minimization of Errors . . . . .	129
6.2.1.7	Typical Applications of Heat Capacity Measurements . . . . .	130
6.2.1.8	Heat Capacity Measurements with Temperature Modulated DSC . . . . .	132
6.2.2	The Investigation of Reactions . . . . .	132
6.2.2.1	Determination of Heats of reaction . . . . .	133
6.2.2.2	Kinetic Investigations . . . . .	139
6.2.2.2.1	Introduction and Definitions . . . . .	139
6.2.2.2.2	Experimental Preconditions for a Reliable Kinetic Analysis . . . . .	141
6.2.2.2.3	Isothermal or Non-isothermal Reaction Mode? . . . . .	143
6.2.2.2.4	Thermal Activation of the Sample or Activation by High Energy Radiation . . . . .	146
6.2.2.2.5	Remarks on the Influence of Different Phases . . . . .	149
6.2.2.2.6	Evaluation of Overall Rate Laws and Formal Kinetic Parameters . . . . .	149

6.2.2.2.7	Determination of the True Reaction Mechanism . . . . .	152
6.2.2.2.8	Selected Examples . . . . .	153
<b>6.2.3</b>	<b>The Glass Transition Process . . . . .</b>	<b>160</b>
6.2.3.1	The Phenomenology of the Glass Transition . . . . .	160
6.2.3.2	The Nature of the Glass Transition and Consequences for DSC-Measurements . . . . .	161
6.2.3.3	Definition and Determination of the Glass Transition <b>Temperature <math>T_g</math></b> . . . . .	163
6.2.3.3.1	Conventional Glass Transition Temperatures . . . . .	163
6.2.3.3.2	The Thermodynamically Defined Glass Transition Temperature . .	165
6.2.3.4	Applications of Glass Transition Measurements . . . . .	171
<b>7</b>	<b>Evaluation of the Performance of a Differential Scanning Calorimeter . . . . .</b>	<b>181</b>
7.1	Characterization of the Complete Instrument . . . . .	181
7.2	Characterization of the Measuring System . . . . .	181
7.3	Characterization of the Results of a Measurement . . . . .	186
7.4	Check List for <b>DSCs</b> . . . . .	188
<b>Appendix 1</b>	<b>. . . . .</b>	<b>189</b>
<b>Appendix 2</b>	<b>. . . . .</b>	<b>193</b>
<b>References</b>	<b>. . . . .</b>	<b>211</b>
<b>Subject Index</b>	<b>. . . . .</b>	<b>217</b>