

Contents

Preface.	ix
Chapter 1. Crystal Orientation.	
1.1 Crystallography	1
1.2 Orientation	8
References.	18
Chapter 2. Crystallographic Defects and Their Observation	21
2.1 Point Defects.	21
2.2 Dislocations	25
2.3 Stacking Faults.	36
2.4 Twins	40
2.5 Lineage	41
2.6 Grains and Grain Boundaries.	42
2.7 Inclusions	43
2.8 Lattice Stress and Strain.	44
2.9 Mechanical Surface Damage.	49
2.10 Shape Defects.	52
2.11 Radiation Damage.	502
Re~re~n..	~
Chapter 3. Resistivity and Carrier Concentration Measurements.	65
3.1 General Considerations.	65
3.2 Basic Methods.	67
3.3 Two- and Four-Point Probe Instrumentation.	75
3.4 Errors in Two- and Four-Point Measurement.	79
3.5 Spreading Resistance.	82
3.6 Noncontacting Resistivity Methods.	84
3.7 Carrier Concentration.	85
3.8 Resistivity Profiling.	88
References	93
Chapter 4. Lifetime.	105
4.1 Introduction.	105
4.2 Photoconductive Decay.	107
4.3 Alternate Injection Methods	113
4.4 Photoconductive Lifetime.	114
4.5 Photoconductive Lifetime.	114
4.6 Surface Photoconductive Lifetime.	115
4.7 Photoconductive Lifetime.	117

~.~	Dilru,i"n-L:nglh \k:bur.:m.n!	liS
~.7	Dril1	l~J
~.1tJ	\li.:dlan':"lb ~\khd,	l~I
	R.:krem:e,	l~I

Chapter 5. Mobility, Hall, and Type Measurements.	131
5.1 \I"hilil\	I~I
:\.1 Hall Elr'::1	133
5.~ C1ndudi\ il~ T\ p.:	I~
R~ft:fl:n!t'::"o	Ir
Chapter 6. Thickness Measurements.	153
6.1 Imrodu' lion,	153
6.~ \li.:rometer, and Other Gage,	15~
6.3 Ah,orpti,)n \kthod,	156
6.4 Ellip,ometr~	158
6.5 Imerferen.:e Effe.:1S . . .	165
6.6 Bevel \leasuremems by Interferometry and Other \kthods	175
6.7 Step-Height \leasuremems	ISI
6.8 High Power \li.:ros.:ope plus Visible B"undaries	181
6.9 Weight Dilferemial	IS I
6.10 Crystallographi.: \lethods.	18~
6.11 \li"dlanenus \kthods for \ktalli.: Films	IS3
Rderen.:es	183
Chapter 7. Preparation of Samples for Microscopic Examination.	187
7.1 Sectioning..	187
7.2 Chemical Treatmms	196
7.3 Delineation	200
References.	214
Chapter 8. Microscopy and Photography.	217
8.1 Basic Optics.	217
8.2 Optical Image Quality.	TII
8.3 Specialized Opti.:al Equipment.	228
8.4 Photography.....	235
References	241
Chapter 9. The Electron Microscope and Other Analytical Instruments.	243
9.1 Ele.:tron \li.:roscopy. General.	243
9.2 Transmission \licrosopy	244
9.3 The Scanning \li.:roscope	2~6
9.4 Electron Diffraction.	252
9.5 X-Rays	254
9.6 Electron Spectroscopy	259
9.7 Optical Spectroscopy.	262
9.8 \lass Spectroscopy.	265
9.9 Ion Backscattering	266
9.10 Radioactive \lethods "....."	267
References.	268
<i>Index.</i>	275