

4.3.2.	Electron Detectors	127
4.3.2.1.	Everhart-Thornley Detector	128
4.3.2.2.	“Through-the-Lens” (TTL) Detector	132
4.3.2.3.	Dedicated Backscattered Electron Detectors	133
4.4.	The Roles of the Specimen and Detector in Contrast Formation	139
4.4.1.	Contrast	139
4.4.2.	Compositional (Atomic Number) Contrast	141
4.4.2.1.	Introduction	141
4.4.2.2.	Compositional Contrast with Backscattered Electrons	141
4.4.3.	Topographic Contrast	145
4.4.3.1.	Origins of Topographic Contrast	146
4.4.3.2.	Topographic Contrast with the Everhart- Thornley Detector	147
4.4.3.3.	Light-Optical Analogy	151
4.4.3.4.	Interpreting Topographic Contrast with Other Detectors	158
4.5.	Image Quality	173
4.6.	Image Processing for the Display of Contrast Information	178
4.6.1.	The Signal Chain	178
4.6.2.	The Visibility Problem	180
4.6.3.	Analog and Digital Image Processing	182
4.6.4.	Basic Digital Image Processing	184
4.6.4.1.	Digital Image Enhancement	187
4.6.4.2.	Digital Image Measurements	192
References	192

5.	Special Topics in Scanning Electron Microscopy	195
5.1.	High-Resolution Imaging	195
5.1.1.	The Resolution Problem	195
5.1.2.	Achieving High Resolution at High Beam Energy	197
5.1.3.	High-Resolution Imaging at Low Voltage	201
5.2.	STEM-in-SEM: High Resolution for the Special Case of Thin Specimens	203
5.3.	Surface Imaging at Low Voltage	207
5.4.	Making Dimensional Measurements in the SEM	209
5.5.	Recovering the Third Dimension: Stereomicroscopy	212
5.5.1.	Qualitative Stereo Imaging and Presentation	212
5.5.2.	Quantitative Stereo Microscopy	217
5.6.	Variable-Pressure and Environmental SEM	220
5.6.1.	Current Instruments	221
5.6.2.	Gas in the Specimen Chamber	222
5.6.2.1.	Units of Gas Pressure	222
5.6.2.2.	The Vacuum System	222
5.6.3.	Electron Interactions with Gases	225
5.6.4.	The Effect of the Gas on Charging	231
5.6.5.	Imaging in the ESEM and the VPSEM	236
5.6.6.	X-Ray Microanalysis in the Presence of a Gas	241
5.7.	Special Contrast Mechanisms	242
5.7.1.	Electric Fields	243
5.7.2.	Magnetic Fields	245

	5.7.2.1. Type 1 Magnetic Contrast	245
	5.7.2.2. Type 2 Magnetic Contrast	247
	5.7.3. Crystallographic Contrast	247
5.8.	Electron Backscatter Patterns	256
	5.8.1. Origin of EBSD Patterns	260
	5.8.2. Hardware for EBSD	262
	5.8.3. Resolution of EBSD	264
	5.8.3.1. Lateral Spatial Resolution	264
	5.8.3.2. Depth Resolution	266
	5.8.4. Applications	267
	5.8.4.1. Orientation Mapping	267
	5.8.4.2. Phase Identification	267
	References	269
6.	Generation of X-Rays in the SEM Specimen	271
6.1.	Continuum X-Ray Production (Bremsstrahlung)	271
6.2.	Characteristic X-Ray Production	274
	6.2.1. Origin	274
	6.2.2. Fluorescence Yield	275
	6.2.3. Electron Shells	276
	6.2.4. Energy-Level Diagram	277
	6.2.5. Electron Transitions	277
	6.2.6. Critical Ionization Energy	278
	6.2.7. Moseley's Law	279
	6.2.8. Families of Characteristic Lines	279
	6.2.9. Natural Width of Characteristic X-Ray Lines	281
	6.2.10. Weights of Lines	282
	6.2.11. Cross Section for Inner Shell Ionization	283
	6.2.12. X-Ray Production in Thin Foils	284
	6.2.13. X-Ray Production in Thick Targets	284
	6.2.14. X-Ray Peak-to-Background Ratio	285
6.3.	Depth of X-Ray Production (X-Ray Range)	286
	6.3.1. Anderson-Hasler X-Ray Range	286
	6.3.2. X-Ray Spatial Resolution	286
	6.3.3. Sampling Volume and Specimen Homogeneity	288
	6.3.4. Depth Distribution of X-Ray Production, $\phi(\rho z)$	288
6.4.	X-Ray Absorption	289
	6.4.1. Mass Absorption Coefficient for an Element	290
	6.4.2. Effect of Absorption Edge on Spectrum	291
	6.4.3. Absorption Coefficient for Mixed-Element Absorbers	291
6.5.	X-Ray Fluorescence	292
	6.5.1. Characteristic Fluorescence	293
	6.5.2. Continuum Fluorescence	294
	6.5.3. Range of Fluorescence Radiation	295
	References	295
7.	X-Ray Spectral Measurement: EDS and WDS	297
7.1.	Introduction	297
7.2.	Energy-Dispersive X-Ray Spectrometer	297
	7.2.1. Operating Principles	297

7.2.2.	The Detection Process	301
7.2.3.	Charge-to-Voltage Conversion	302
7.2.4.	Pulse-Shaping Linear Amplifier and Pileup Rejection Circuitry	303
7.2.5.	The Computer X-Ray Analyzer	308
7.2.6.	Digital Pulse Processing	311
7.2.7.	Spectral Modification Resulting from the Detection Process	312
	7.2.7.1. Peak Broadening	312
	7.2.7.2. Peak Distortion	316
	7.2.7.3. Silicon X-Ray Escape Peaks	317
	7.2.7.4. Absorption Edges	318
	7.2.7.5. Silicon Internal Fluorescence Peak	320
7.2.8.	Artifacts from the Detector Environment	321
7.2.9.	Summary of EDS Operation and Artifacts	322
7.3.	Wavelength-Dispersive Spectrometer	323
	7.3.1. Introduction	323
	7.3.2. Basic Description	324
	7.3.3. Diffraction Conditions	325
	7.3.4. Diffracting Crystals	327
	7.3.5. The X-Ray Proportional Counter	330
	7.3.6. Detector Electronics	333
7.4.	Comparison of Wavelength-Dispersive Spectrometers with Conventional Energy-Dispersive Spectrometers	340
	7.4.1. Geometric Collection Efficiency	340
	7.4.2. Quantum Efficiency	341
	7.4.3. Resolution	342
	7.4.4. Spectral Acceptance Range	344
	7.4.5. Maximum Count Rate	344
	7.4.6. Minimum Probe Size	344
	7.4.7. Speed of Analysis	346
	7.4.8. Spectral Artifacts	346
7.5.	Emerging Detector Technologies	347
	7.5.1. X-Ray Microcalorimetry	347
	7.5.2. Silicon Drift Detectors	349
	7.5.3. Parallel Optic Diffraction-Based Spectrometers	350
	References	353
8.	Qualitative X-Ray Analysis	355
8.1.	Introduction	355
8.2.	EDS Qualitative Analysis	357
	8.2.1. X-Ray Peaks	357
	8.2.2. Guidelines for EDS Qualitative Analysis	366
	8.2.2.1. General Guidelines for EDS Qualitative Analysis	368
	8.2.2.2. Specific Guidelines for EDS Qualitative Analysis	369
	8.2.3. Examples of Manual EDS Qualitative Analysis	372
	8.2.4. Pathological Overlaps in EDS Qualitative Analysis	374

8.2.5.	Advanced Qualitative Analysis: Peak Stripping . . .	379
8.2.6.	Automatic Qualitative EDS Analysis	381
8.3.	WDS Qualitative Analysis	382
8.3.1.	Wavelength-Dispersive Spectrometry of X-Ray Peaks	382
8.3.2.	Guidelines for WDS Qualitative Analysis	388
References	390
9.	Quantitative X-Ray Analysis: The Basics	391
9.1.	Introduction	391
9.2.	Advantages of Conventional Quantitative X-Ray Microanalysis in the SEM	392
9.3.	Quantitative Analysis Procedures: Flat-Polished Samples . . .	393
9.4.	The Approach to X-Ray Quantitation: The Need for Matrix Corrections	402
9.5.	The Physical Origin of Matrix Effects	403
9.6.	ZAF Factors in Microanalysis	404
9.6.1.	Atomic number effect, Z	404
9.6.1.1.	Effect of Backscattering (R) and Energy Loss (S)	404
9.6.1.2.	X-Ray Generation with Depth, $\phi(\rho z)$	406
9.6.2.	X-Ray Absorption Effect, A	411
9.6.3.	X-Ray Fluorescence, F	415
9.7.	Calculation of ZAF Factors	416
9.7.1.	Atomic Number Effect, Z	417
9.7.2.	Absorption correction, A	417
9.7.3.	Characteristic Fluorescence Correction, F	418
9.7.4.	Calculation of ZAF	418
9.7.5.	The Analytical Total	420
9.8.	Practical Analysis	421
9.8.1.	Examples of Quantitative Analysis	421
9.8.1.1.	Al-Cu Alloys	421
9.8.1.2.	Ni-10 wt% Fe Alloy	423
9.8.1.3.	Ni-38.5 wt% Cr-3.0 wt% Al Alloy	423
9.8.1.4.	Pyroxene: 53.5 wt% SiO ₂ , 1.11 wt% Al ₂ O ₃ , 0.62 wt% Cr ₂ O ₃ , 9.5 wt% FeO, 14.1 wt% MgO, and 21.2 wt% CaO	425
9.8.2.	Standardless Analysis	427
9.8.2.1.	First-Principles Standardless Analysis	429
9.8.2.2.	"Fitted-Standards" Standardless Analysis	433
9.8.3.	Special Procedures for Geological Analysis	436
9.8.3.1.	Introduction	436
9.8.3.2.	Formulation of the Bence-Albee Procedure	437
9.8.3.3.	Application of the Bence-Albee Procedure	438
9.8.3.4.	Specimen Conductivity	439
9.8.4.	Precision and Sensitivity in X-Ray Analysis	440
9.8.4.1.	Statistical Basis for Calculating Precision and Sensitivity	440
9.8.4.2.	Precision of Composition	442
9.8.4.3.	Sample Homogeneity	444
9.8.4.4.	Analytical Sensitivity	445

	9.8.4.5. Trace Element Analysis	446
	9.8.4.6. Trace Element Analysis Geochronologic Applications	448
	9.8.4.7. Biological and Organic Specimens	449
	References	449
10.	Special Topics in Electron Beam X-Ray Microanalysis	453
10.1.	Introduction	453
10.2.	Thin Film on a Substrate	454
10.3.	Particle Analysis	462
	10.3.1. Particle Mass Effect	463
	10.3.2. Particle Absorption Effect	463
	10.3.3. Particle Fluorescence Effect	464
	10.3.4. Particle Geometric Effects	465
	10.3.5. Corrections for Particle Geometric Effects	466
	10.3.5.1. The Consequences of Ignoring Particle Effects	466
	10.3.5.2. Normalization	466
	10.3.5.3. Critical Measurement Issues for Particles	468
	10.3.5.4. Advanced Quantitative Methods for Particles	470
10.4.	Rough Surfaces	476
	10.4.1. Introduction	476
	10.4.2. Rough Specimen Analysis Strategy	479
	10.4.2.1. Reorientation	479
	10.4.2.2. Normalization	479
	10.4.2.3. Peak-to-Background Method	479
10.5.	Beam-Sensitive Specimens (Biological, Polymeric)	480
	10.5.1. Thin-Section Analysis	480
	10.5.2. Bulk Biological and Organic Specimens	483
10.6.	X-Ray Mapping	485
	10.6.1. Relative Merits of WDS and EDS for Mapping	486
	10.6.2. Digital Dot Mapping	487
	10.6.3. Gray-Scale Mapping	488
	10.6.3.1. The Need for Scaling in Gray-Scale Mapping	489
	10.6.3.2. Artifacts in X-Ray Mapping	491
	10.6.4. Compositional Mapping	492
	10.6.4.1. Principles of Compositional Mapping	492
	10.6.4.2. Advanced Spectrum Collection Strategies for Compositional Mapping	494
	10.6.5. The Use of Color in Analyzing and Presenting X-Ray Maps	497
	10.6.5.1. Primary Color Superposition	497
	10.6.5.2. Pseudocolor Scales	497
10.7.	Light Element Analysis	499
	10.7.1. Optimization of Light Element X-Ray Generation	499
	10.7.2. X-Ray Spectrometry of the Light Elements	503
	10.7.2.1. Si EDS	503
	10.7.2.2. WDS	507
	10.7.3. Special Measurement Problems for the Light Elements	511
	10.7.3.1. Contamination	511

	10.7.3.2. Overvoltage Effects	512
	10.7.3.3. Absorption Effects	514
	10.7.4. Light Element Quantification	515
10.8.	Low-Voltage Microanalysis	518
	10.8.1. "Low-Voltage" versus "Conventional" Microanalysis	518
	10.8.2. X-Ray Production Range	519
	10.8.2.1. Contribution of the Beam Size to the X-Ray Analytical Resolution	520
	10.8.2.2. A Consequence of the X-Ray Range under Low-Voltage Conditions	523
	10.8.3. X-Ray Spectrometry in Low-Voltage Microanalysis	525
	10.8.3.1. The Oxygen and Carbon Problem	526
	10.8.3.2. Quantitative X-Ray Microanalysis at Low Voltage	528
10.9.	Report of Analysis	531
	References	535

11. Specimen Preparation of Hard Materials: Metals, Ceramics, Rocks, Minerals, Microelectronic and Packaged Devices, Particles, and Fibers

	11.1. Metals	537
	11.1.1. Specimen Preparation for Surface Topography	537
	11.1.2. Specimen Preparation for Microstructural and Microchemical Analysis	538
	11.1.2.1. Initial Sample Selection and Specimen Preparation Steps	538
	11.1.2.2. Final Polishing Steps	539
	11.1.2.3. Preparation for Microanalysis	540
11.2.	Ceramics and Geological Samples	541
	11.2.1. Initial Specimen Preparation: Topography and Microstructure	542
	11.2.2. Mounting and Polishing for Microstructural and Microchemical Analysis	542
	11.2.3. Final Specimen Preparation for Microstructural and Microchemical Analysis	542
11.3.	Microelectronics and Packages	543
	11.3.1. Initial Specimen Preparation	543
	11.3.2. Polishing	544
	11.3.3. Final Preparation	545
11.4.	Imaging of Semiconductors	545
	11.4.1. Voltage Contrast	546
	11.4.2. Charge Collection	546
11.5.	Preparation for Electron Diffraction in the SEM	547
	11.5.1. Channeling Patterns and Channeling Contrast	547
	11.5.2. Electron Backscatter Diffraction	547
11.6.	Special Techniques	551
	11.6.1. Plasma Cleaning	551
	11.6.2. Focused-Ion-Beam Sample Preparation for SEM	553
	11.6.2.1. Application of FIB for Semiconductors	554
	11.6.2.2. Applications of FIB in Materials Science	555

11.7. Particles and Fibers	557
11.7.1. Particle Substrates and Supports	559
11.7.1.1. Bulk Particle Substrates	559
11.7.1.2. Thin Particle Supports	560
11.7.2. Particle Mounting Techniques	560
11.7.3. Particles Collected on Filters	562
11.7.4. Particles in a Solid Matrix	563
11.7.5. Transfer of Individual Particles	563
References	564
12. Specimen Preparation of Polymer Materials	565
12.1. Introduction	565
12.2. Microscopy of Polymers	565
12.2.1. Radiation Effects	566
12.2.2. Imaging Compromises	567
12.2.3. Metal Coating Polymers for Imaging	567
12.2.4. X-Ray Microanalysis of Polymers	570
12.3. Specimen Preparation Methods for Polymers	570
12.3.1. Simple Preparation Methods	571
12.3.2. Polishing of Polymers	571
12.3.3. Microtomy of Polymers	572
12.3.4. Fracture of Polymer Materials	573
12.3.5. Staining of Polymers	576
12.3.5.1. Osmium Tetroxide and Ruthenium Tetroxide	578
12.3.5.2. Ebonite	578
12.3.5.3. Chlorosulfonic Acid and Phosphotungstic Acid	578
12.3.6. Etching of Polymers	579
12.3.7. Replication of Polymers	580
12.3.8. Rapid Cooling and Drying Methods for Polymers	580
12.3.8.1. Simple Cooling Methods	580
12.3.8.2. Freeze-Drying	581
12.3.8.3. Critical-Point Drying	581
12.4. Choosing Specimen Preparation Methods	581
12.4.1. Fibers	582
12.4.2. Films and Membranes	582
12.4.3. Engineering Resins and Plastics	583
12.4.4. Emulsions and Adhesives	587
12.5. Problem-Solving Protocol	588
12.6. Image Interpretation and Artifacts	589
References	590
13. Ambient-Temperature Specimen Preparation of Biological Material	591
13.1. Introduction	591
13.2. Preparative Procedures for the Structural SEM of Single Cells, Biological Particles, and Fibers	592
13.2.1. Particulate, Cellular, and Fibrous Organic Material	592
13.2.2. Dry Organic Particles and Fibers	593

13.2.2.1.	Organic Particles and Fibers on a Filter	594
13.2.2.2.	Organic Particles and Fibers Entrained within a Filter	594
13.2.2.3.	Organic Particulate Matter Suspended in a Liquid	594
13.2.2.4.	Manipulating Individual Organic Particles	595
13.3.	Preparative Procedures for the Structural Observation of Large Soft Biological Specimens	596
13.3.1.	Introduction	596
13.3.2.	Sample Handling before Fixation	596
13.3.3.	Fixation	596
13.3.4.	Microwave Fixation	597
13.3.5.	Conductive Infiltration	597
13.3.6.	Dehydration	597
13.3.7.	Embedding	602
13.3.8.	Exposing the Internal Contents of Bulk Specimens	602
13.3.8.1.	Mechanical Dissection	602
13.3.8.2.	High-Energy-Beam Surface Erosion	602
13.3.8.3.	Chemical Dissection	603
13.3.8.4.	Surface Replicas and Corrosion Casts	604
13.3.9.	Specimen Supports and Methods of Sample Attachment	605
13.3.10.	Artifacts	607
13.4.	Preparative Procedures for the <i>in Situ</i> Chemical Analysis of Biological Specimens in the SEM	607
13.4.1.	Introduction	607
13.4.2.	Preparative Procedures for Elemental Analysis Using X-Ray Microanalysis	608
13.4.2.1.	The Nature and Extent of the Problem	608
13.4.2.2.	Types of Sample That May be Analyzed	609
13.4.2.3.	The General Strategy for Sample Preparation	609
13.4.2.4.	Criteria for Judging Satisfactory Sample Preparation	610
13.4.2.5.	Fixation and Stabilization	610
13.4.2.6.	Precipitation Techniques	611
13.4.2.7.	Procedures for Sample Dehydration, Embedding, and Staining	611
13.4.2.8.	Specimen Supports	611
13.4.3.	Preparative Procedures for Localizing Molecules Using Histochemistry	612
13.4.3.1.	Staining and Histochemical Methods	612
13.4.3.2.	Atomic Number Contrast with Backscattered Electrons	613
13.4.4.	Preparative Procedures for Localizing Macromolecules Using Immunocytochemistry	614
13.4.4.1.	Introduction	614
13.4.4.2.	The Antibody–Antigen Reaction	614
13.4.4.3.	General Features of Specimen Preparation for Immunocytochemistry	615
13.4.4.4.	Imaging Procedures in the SEM	616
References	618

14. Low-Temperature Specimen Preparation	621
14.1. Introduction	621
14.2. The Properties of Liquid Water and Ice	622
14.3. Conversion of Liquid Water to Ice	623
14.4. Specimen Pretreatment before Rapid (Quench) Cooling	624
14.4.1. Minimizing Sample Size and Specimen Holders	624
14.4.2. Maximizing Undercooling	626
14.4.3. Altering the Nucleation Process	626
14.4.4. Artificially Depressing the Sample Freezing Point	626
14.4.5. Chemical Fixation	626
14.5. Quench Cooling	627
14.5.1. Liquid Cryogenes	627
14.5.2. Solid Cryogenes	628
14.5.3. Methods for Quench Cooling	629
14.5.4. Comparison of Quench Cooling Rates	630
14.6. Low-Temperature Storage and Sample Transfer	631
14.7. Manipulation of Frozen Specimens: Cryosectioning, Cryofracturing, and Cryoplaning	631
14.7.1. Cryosectioning	631
14.7.2. Cryofracturing	633
14.7.3. Cryopolishing or Cryoplaning	634
14.8. Ways to Handle Frozen Liquids within the Specimen	635
14.8.1. Frozen-Hydrated and Frozen Samples	636
14.8.2. Freeze-Drying	637
14.8.2.1. Physical Principles Involved in Freeze-Drying	637
14.8.2.2. Equipment Needed for Freeze-Drying	638
14.8.2.3. Artifacts Associated with Freeze-Drying	639
14.8.3. Freeze Substitution and Low-Temperature Embedding	639
14.8.3.1. Physical Principles Involved in Freeze Substitution and Low-Temperature Embedding	639
14.8.3.2. Equipment Needed for Freeze Substitution and Low-Temperature Embedding	640
14.9. Procedures for Hydrated Organic Systems	640
14.10. Procedures for Hydrated Inorganic Systems	641
14.11. Procedures for Nonaqueous Liquids	642
14.12. Imaging and Analyzing Samples at Low Temperatures	643
References	644
15. Procedures for Elimination of Charging in Nonconducting Specimens	647
15.1. Introduction	647
15.2. Recognizing Charging Phenomena	650
15.3. Procedures for Overcoming the Problems of Charging	656
15.4. Vacuum Evaporation Coating	657
15.4.1. High-Vacuum Evaporation Methods	658
15.4.2. Low-Vacuum Evaporation Methods	661

15.5. Sputter Coating	661
15.5.1. Plasma Magnetron Sputter Coating	662
15.5.2. Ion Beam and Penning Sputtering	664
15.6. High-Resolution Coating Methods	667
15.7. Coating for Analytical Studies	669
15.8. Coating Procedures for Samples Maintained at Low Temperatures	669
15.9. Coating Thickness	670
15.10. Damage and Artifacts on Coated Samples	672
15.11. Summary of Coating Guidelines	673
References	673

Index	675
------------------------	------------

Enhancements CD

CONT