

---

# *Contents*

---

|          |  |           |
|----------|--|-----------|
| <b>1</b> | <b>Introduction .....</b>  | <b>1</b>  |
| 1.1      | Residual Stress: Friend or Foe? .....                            | 1         |
| 1.2      | Historical Development of Stress Measurement by Diffraction..... | 2         |
| 1.2.1    | Laboratory X-Ray Diffraction.....                                | 3         |
| 1.2.2    | Synchrotron X-Ray Diffraction.....                               | 5         |
| 1.2.3    | Neutron Diffraction .....  | 5         |
| 1.3      | Special Characteristics of Neutron Strain Measurement .....      | 6         |
| 1.4      | Nature and Origin of Residual Stress .....                       | 10        |
| 1.4.1    | Macrostresses and Microstresses .....                            | 11        |
| 1.4.2    | Measurement of Macrostresses and Microstresses.....              | 14        |
| 1.4.2.1  | Diffraction Techniques .....                                     | 15        |
| 1.4.2.2  | Other Measurement Techniques.....                                | 16        |
| 1.5      | Effects of Residual Stress.....                                  | 17        |
| 1.5.1    | Static Loading .....   | 17        |
| 1.5.2    | Fatigue Loading.....   | 18        |
|          | References.....  | 21        |
| <b>2</b> | <b>Fundamentals of Neutron Diffraction.....</b>                  | <b>25</b> |
| 2.1      | Introduction .....   | 25        |
| 2.2      | Scattering and Absorption of Neutrons and X-Rays by Atoms .....  | 27        |
| 2.2.1    | Neutron Scattering .....   | 27        |
| 2.2.1.1  | Coherent Scattering Cross-Section .....                          | 30        |
| 2.2.1.2  | Incoherent Scattering Cross-Section .....                        | 30        |
| 2.2.1.3  | Absorption Cross-Section .....                                   | 31        |
| 2.2.1.4  | Tabulation of Neutron Cross-Sections.....                        | 32        |
| 2.2.2    | X-Ray Scattering .....   | 32        |
| 2.3      | Neutron Diffraction from Crystalline Solids.....                 | 34        |
| 2.3.1    | Crystal Lattice .....  | 35        |
| 2.3.2    | Diffraction from Crystal Lattice Planes.....                     | 37        |
| 2.3.2.1  | Observation of Diffraction Peaks .....                           | 39        |
| 2.3.3    | Reciprocal Lattice Approach to Diffraction Theory .....          | 40        |
| 2.3.3.1  | Reciprocal Lattice.....  | 40        |
| 2.3.3.2  | Neutron Coherent Elastic Cross-Section .....                     | 41        |
| 2.3.4    | Lattice Plane Spacings .....                                     | 46        |
| 2.3.4.1  | Orthogonal Crystal Structures.....                               | 47        |
| 2.3.4.2  | Hexagonal Structures .....                                       | 48        |
| 2.3.4.3  | Lower Symmetry Structures .....                                  | 48        |
| 2.3.5    | Diffracted Intensity .....                                       | 49        |

|          |  |           |
|----------|--|-----------|
| 2.3.6    | Scattering from Engineering Materials.....                           | 52        |
| 2.3.6.1  | Scattering from Elements .....                                       | 52        |
| 2.3.6.2  | Scattering from Alloys .....   | 52        |
| 2.3.6.3  | Application to Titanium Alloys.....                                  | 53        |
| 2.3.7    | Macroscopic Cross-Section .....                                      | 53        |
| 2.3.7.1  | Elements .....   | 53        |
| 2.3.7.2  | Alloys.....  | 54        |
| 2.4      | Penetration of Neutron Beams .....                                   | 55        |
| 2.5      | Effects of Lattice Vibrations .....                                  | 56        |
| 2.6      | Extinction, Texture, and Multiple Scattering .....                   | 58        |
| 2.6.1    | Extinction.....  | 58        |
| 2.6.2    | Texture.....   | 59        |
| 2.6.3    | Multiple Scattering.....   | 60        |
|          | References.....  | 63        |
| <b>3</b> | <b>Diffraction Techniques and Instrument Design .....</b>            | <b>65</b> |
| 3.1      | Neutron Sources.....   | 65        |
| 3.1.1    | Steady-State Reactor Neutron Source.....                             | 66        |
| 3.1.1.1  | Moderation.....  | 67        |
| 3.1.1.2  | Neutron Guide Tubes.....   | 69        |
| 3.1.1.3  | Neutron Lenses .....   | 73        |
| 3.1.2    | Time-Pulsed Neutron Source .....                                     | 73        |
| 3.1.3    | Safety .....   | 77        |
| 3.2      | Diffractometers for Strain Measurement .....                         | 78        |
| 3.2.1    | Reactor-Based Continuous Beam Instrument for Strain Measurement..... | 79        |
| 3.2.1.1  | Basic Instrument .....   | 79        |
| 3.2.1.2  | Instrument Construction .....  | 83        |
| 3.2.1.3  | Monochromator and Choice of Wavelength .....                         | 84        |
| 3.2.1.4  | Collimation .....  | 88        |
| 3.2.1.5  | Apertures and Beam Area Definition.....                              | 89        |
| 3.2.1.6  | Shielding.....   | 91        |
| 3.2.2    | Time-Pulsed Beam Instrument for Strain Measurement.....              | 92        |
| 3.2.2.1  | Time-Pulsed Neutron Beams on Reactors .....                          | 92        |
| 3.2.2.2  | Time-Pulsed Neutron Beams from Pulsed Sources .....                  | 93        |
| 3.2.2.3  | Instruments on a Spallation Source.....                              | 96        |
| 3.2.2.4  | Collimation .....  | 99        |
| 3.3      | Neutron Detectors .....  | 100       |
| 3.3.1    | Position-Sensitive Detectors and Detector Arrays.....                | 101       |
| 3.4      | The Instrumental Resolution .....                                    | 103       |
| 3.4.1    | Continuous Beam Instrument .....                                     | 104       |
| 3.4.2    | Time-Pulsed Beam Instrument.....                                     | 107       |
| 3.5      | Instrument Gauge Volumes .....                                       | 108       |
| 3.5.1    | Instrument Reference Point .....                                     | 109       |

|         |  |     |
|---------|--|-----|
| 3.5.2   | Gauge Volume .....   | 109 |
| 3.5.2.1 | Nominal Gauge Volume .....   | 110 |
| 3.5.2.2 | Instrumental Gauge Volume .....  | 111 |
| 3.5.2.3 | Definition of Instrumental Gauge Volume When<br>Using a Position-Sensitive Detector..... | 114 |
| 3.6     | Sampled Gauge Volume and Effective Measurement Position .....                            | 114 |
| 3.6.1   | Sampled Gauge Volume.....  | 114 |
| 3.6.2   | Effects of Beam Attenuation in Sample.....   | 116 |
| 3.6.2.1 | Geometric and Attenuation Shifts of Effective<br>Centroid of Sampled Gauge Volume.....   | 119 |
| 3.6.3   | Sample Positioning .....   | 120 |
| 3.6.3.1 | Sample Positioning, Orientation, and Movement....  | 120 |
| 3.6.3.2 | Mounting the Sample.....   | 123 |
| 3.6.4   | Anomalous Angular Shifts Due to Surface Effects .....                                    | 126 |
| 3.6.4.1 | Corrections for Anomalous Angle Shifts.....  | 131 |
| 3.6.4.2 | Minimizing Anomalous Angle Shifts .....  | 134 |
| 3.7     | Specialized Instruments for Strain Measurement .....                                     | 136 |
| 3.7.1   | Triple-Axis Spectrometer.....  | 136 |
| 3.7.2   | Use of Horizontally Curved Silicon Crystals .....  | 138 |
| 3.7.3   | Specialized Time-of-Flight Techniques .....  | 140 |
| 3.7.4   | Transmission Techniques .....  | 142 |
|         | References.....  | 144 |

## **4 Practical Aspects of Strain Measurement Using Neutron Diffraction .....** 149

|         |  |     |
|---------|--|-----|
| 4.1     | Introduction .....   | 149 |
| 4.2     | Measurement of Diffraction Bragg Peak Profile.....                 | 152 |
| 4.2.1   | Choosing an Appropriate Gauge Volume.....                          | 152 |
| 4.2.2   | Choosing an Appropriate Reflection .....                           | 153 |
| 4.2.2.1 | Elastic Regime .....   | 154 |
| 4.2.2.2 | Plastic Regime .....   | 154 |
| 4.2.2.3 | Avoidance of Anomalous Shifts of Angle Due to<br>Bragg Edges ..... | 155 |
| 4.2.2.4 | Measurement of Many Peaks in a Diffraction<br>Pattern.....         | 157 |
| 4.2.3   | Scanning the Diffraction Peak.....                                 | 157 |
| 4.3     | Analyzing Bragg Peak Profiles.....                                 | 157 |
| 4.3.1   | Expressions for Peak Profiles .....                                | 159 |
| 4.3.1.1 | Symmetric Peaks from Continuous Source<br>Diffractometers.....     | 159 |
| 4.3.1.2 | Asymmetric Peaks from Time-Pulsed Source<br>Instruments .....      | 161 |
| 4.3.2   | Fitting a Profile to a Single Diffraction Peak.....                | 162 |
| 4.4     | Accuracy of Diffraction Peak Center Determination.....             | 164 |
| 4.4.1   | Accuracy of Fitted Parameters.....                                 | 164 |

|                 |  |     |
|-----------------|--|-----|
| 4.4.1.1         | Uncertainty in Case of Negligible Background .....                         | 164 |
| 4.4.1.2         | Effects of Background on Strain Uncertainty .....                          | 166 |
| 4.4.1.3         | Systematic Uncertainties.....  | 169 |
| 4.4.2           | Time Required to Achieve a Given Accuracy in Peak Center Measurement ..... | 169 |
| 4.4.2.1         | Measuring at Positions Deep within a Sample .....                          | 170 |
| 4.4.3           | Analytical and Empirical Studies of Scan Optimization.....                 | 174 |
| 4.4.3.1         | Range of Scan .....  | 174 |
| 4.4.3.2         | Fitting a Sloping Background .....   | 175 |
| 4.4.3.3         | Weighting .....  | 177 |
| 4.4.4           | VAMAS Recommendations on Peak Fitting.....                                 | 178 |
| 4.4.4.1         | Strategy of Peak Fitting .....   | 181 |
| 4.4.5           | Sources of Background Counts.....  | 182 |
| 4.5             | Analysis of Complete Diffraction Profiles for Strain.....                  | 182 |
| 4.6             | Strain-Free Reference .....  | 183 |
| 4.6.1           | Requirement .....  | 183 |
| 4.6.2           | Other Factors That Can Affect Lattice Spacing.....                         | 184 |
| 4.6.3           | Measurement of Reference $d^0$ -Spacing .....                              | 186 |
| 4.6.3.1         | Far-Field Reference .....  | 187 |
| 4.6.3.2         | Powders, Cubes, and Combs .....  | 188 |
| 4.6.3.3         | $d^0$ Measurement Using X-Rays.....  | 192 |
| 4.6.3.4         | $d^0$ Measurement by Neutron Transmission.....                             | 192 |
| 4.6.3.5         | Imposing Stress Balance .....  | 196 |
| 4.7             | Reproducibility Tests.....   | 197 |
| 4.7.1           | Recording Measurement Details.....   | 199 |
| References..... |  | 199 |

|          |  |            |
|----------|--|------------|
| <b>5</b> | <b>Interpretation and Analysis of Lattice Strain Data.....</b>                     | <b>203</b> |
| 5.1      | Inferring Stresses from Lattice Strains .....                                      | 203        |
| 5.1.1    | Basic Continuum Relationship between Strain and Stress ...                         | 203        |
| 5.1.2    | Diffraction-Specific Elastic Constants .....                                       | 206        |
| 5.1.3    | X-Ray Measurement of Stress .....  | 207        |
| 5.2      | Introduction to Mechanics of Crystallite Deformation .....                         | 210        |
| 5.3      | Elastic Anisotropy of Single Crystals.....   | 215        |
| 5.3.1    | Elastic Anisotropy of Cubic Single Crystals .....                                  | 216        |
| 5.3.2    | Elastic Anisotropy of Hexagonal Crystals .....                                     | 221        |
| 5.4      | The Bulk Elastic Response of Polycrystals.....                                     | 222        |
| 5.4.1    | Voigt and Reuss Models for Macroscopic Bulk Properties....                         | 223        |
| 5.4.1.1  | Voigt Model for Bulk Properties .....  | 223        |
| 5.4.1.2  | Reuss Model for Bulk Properties .....  | 224        |
| 5.4.2    | Kröner Model for Macroscopic Bulk Properties .....                                 | 225        |
| 5.5      | <i>hkl</i> -Specific Response in a Polycrystal Undergoing Elastic Deformation..... | 227        |
| 5.5.1    | Voigt and Reuss Models .....   | 227        |
| 5.5.1.1  | Voigt Model .....  | 227        |

|         |  |     |
|---------|--|-----|
| 5.5.1.2 | Reuss Model .....  | 227 |
| 5.5.2   | Kröner Model.....  | 228 |
| 5.6     | <i>hkl</i> -Specific Response in a Polycrystal Undergoing Plastic Deformation..... | 230 |
| 5.6.1   | Elastoplastic Self-Consistent Models .....   | 233 |
| 5.6.2   | Implementation of EPSC Model.....  | 234 |
| 5.6.3   | Predicting Crystallographic Slip.....  | 237 |
| 5.6.4   | EPSC Predictions of Lattice Strains under Plastic Straining ...                    | 239 |
| 5.6.5   | EPSC Predictions of Residual Intergranular Strains .....                           | 242 |
| 5.6.6   | Analysis of Experimental Data .....  | 244 |
| 5.6.6.1 | Uniaxial Tensile Loading of Aluminum .....   | 244 |
| 5.6.6.2 | Uniaxial Tensile Loading of Stainless Steel.....                                   | 246 |
| 5.6.6.3 | Hexagonal Materials .....  | 246 |
| 5.6.6.4 | Cyclical Loading .....   | 248 |
| 5.6.6.5 | Rietveld Analysis of Diffraction Patterns .....                                    | 249 |
| 5.6.7   | Summary.....   | 253 |
| 5.7     | Analysis of Bragg Peak Broadening .....  | 254 |
|         | References.....  | 257 |

|          |  |            |
|----------|--|------------|
| <b>6</b> | <b>Applications to Problems in Materials Science and Engineering.....</b>        | <b>263</b> |
| 6.1      | Introduction .....   | 263        |
| 6.2      | Welded Structures.....   | 265        |
| 6.2.1    | Origin and Nature of Weld Stresses .....   | 266        |
| 6.2.2    | Comparison of Various Stress Measurement Techniques .....                        | 268        |
| 6.2.3    | Challenges to Accurate Neutron Diffraction Measurement of Weldment Stresses..... | 274        |
| 6.2.4    | Examples of Stress Measurement in Weldments .....                                | 278        |
| 6.2.4.1  | Alumino-Thermic Welds .....  | 278        |
| 6.2.4.2  | Manual Metal Arc Repair Welds.....   | 279        |
| 6.2.4.3  | Electron Beam Welds.....   | 281        |
| 6.2.4.4  | Friction-Based Welds.....  | 281        |
| 6.2.5    | Future Directions for Neutron Diffraction Studies of Weldments .....             | 287        |
| 6.2.5.1  | Validation of Finite Element Models.....   | 287        |
| 6.2.5.2  | Postweld Heat Treatment .....  | 288        |
| 6.2.5.3  | Phase Transformations.....   | 288        |
| 6.2.5.4  | Strategies for Improved Lifetime .....   | 289        |
| 6.3      | Composites and Other Multiphase Materials.....                                   | 289        |
| 6.3.1    | Nature and Origins .....   | 289        |
| 6.3.1.1  | Mean Phase-Specific Microstresses .....  | 291        |
| 6.3.2    | Methods for Measurement of Stress in Composites .....                            | 291        |
| 6.3.2.1  | Raman Spectroscopy .....   | 291        |
| 6.3.2.2  | Photoelasticity .....  | 291        |
| 6.3.2.3  | Diffraction Techniques .....   | 292        |

|                 |   |     |
|-----------------|---|-----|
| 6.3.3           | Separation of Different Stress Contributions in Composites ...  | 299 |
| 6.3.4           | Elastic Mismatch Stresses .....   | 301 |
| 6.3.5           | Thermal Microstresses.....  | 303 |
|                 | 6.3.5.1 Particulate Composites .....  | 306 |
|                 | 6.3.5.2 Whisker Composites .....  | 307 |
|                 | 6.3.5.3 Continuous Fiber Composites .....   | 309 |
| 6.3.6           | Plastic Misfit Stresses.....  | 309 |
|                 | 6.3.6.1 Continuous Fiber Metal Matrix Systems .....   | 310 |
| 6.3.7           | Phase Transformation Stresses.....  | 311 |
| 6.3.8           | Microstress-Related Peak Broadening .....   | 312 |
| 6.3.9           | Future Directions for Neutron Diffraction Measurements<br>of Composites .....                               | 314 |
| 6.4             | Plastically Deformed Components and Materials .....   | 316 |
| 6.4.1           | Origin and Nature of Plastic Misfit Stresses .....  | 316 |
| 6.4.2           | Challenges to Accurate Neutron Diffraction Measurement<br>of Stress in Plastically Deformed Components..... | 316 |
| 6.4.3           | Examples of Stress Measurement in Plastically Deformed<br>Materials .....                                   | 317 |
|                 | 6.4.3.1 Studies of Fundamental Aspects of Material<br>Deformation.....                                      | 317 |
|                 | 6.4.3.2 Practical Example of Intergranular Stresses: Bent<br>Monel Tube .....                               | 318 |
|                 | 6.4.3.3 Stress in a Highly Textured Sample .....  | 320 |
|                 | 6.4.3.4 Intergranular Lattice Strain as an Indicator of<br>Macroscopic Plastic Strain.....                  | 322 |
| 6.4.4           | Future Directions for Neutron Diffraction Measurement<br>of Stress in Plastically Deformed Components.....  | 324 |
| 6.5             | Near-Surface Stresses .....   | 324 |
| 6.5.1           | Origin and Nature of Near-Surface Stresses .....  | 325 |
| 6.5.2           | Challenges to Accurate Neutron Diffraction Measurement<br>of Stress Near Surfaces.....                      | 325 |
| 6.5.3           | Examples of Measurement of Stress Near Surfaces .....   | 328 |
|                 | 6.5.3.1 Machining Stresses .....  | 328 |
|                 | 6.5.3.2 Shot-Peening .....  | 329 |
|                 | 6.5.3.3 Carburized Layers .....   | 330 |
| 6.5.4           | Future Directions for Neutron Diffraction Measurement<br>of Stress Near Surfaces.....                       | 332 |
| 6.6             | <i>In Situ</i> and Through-Process or Life Studies .....  | 333 |
| 6.6.1           | Manufacturing Process Studies.....  | 334 |
| 6.6.2           | Heat Treatment .....  | 336 |
| 6.6.3           | Service Life Studies.....   | 338 |
| References..... |   | 340 |
| 7               | The Future.....   | 347 |

|  |     |
|--|-----|
| Symbols and Abbreviations .....  | 349 |
| Glossary .....   | 357 |
| Appendix 1 Note on Reactor Flux Spectrum .....   | 361 |
| Appendix 2 Relation between the Centroid of Sampled<br>Gauge Volume and Translator Reading ..... | 365 |
| Appendix 3 Points for Consideration When Making a<br>Neutron Diffraction Stress Measurement..... | 369 |
| Appendix 4 Macroscopic Scattering Cross-Sections of<br>All Elements .....                        | 379 |
| Index .....  | 385 |