
Contents

Preface.....	xiii
Acknowledgments.....	xv
Author	xvii
Chapter 1 Introduction.....	1
1.1 Materials Science and Engineering.....	1
1.2 Structure	2
1.2.1 Crystal Structure	2
1.2.2 Microstructure.....	3
1.3 Properties.....	4
1.4 Outline of the Book	5
References	5
Chapter 2 X-Ray Diffraction.....	7
2.1 Introduction	7
2.2 Crystal Structure	7
2.2.1 Bravais Lattices	9
2.2.2 Lattice Planes	11
2.2.2.1 Indexing of Planes in Hexagonal Crystals.....	15
2.2.3 Lattice Directions.....	15
2.2.4 Conversion from Three-Index to Four-Index System.....	16
2.2.5 Structure Determination.....	17
2.3 Production of X-Rays	18
2.3.1 Continuous Radiation	20
2.3.2 Characteristic Radiation.....	20
2.4 Absorption of X-Rays.....	23
2.5 Bragg Equation.....	26
2.6 Diffraction Angles.....	31
2.7 Intensities of Diffracted Beams.....	35
2.7.1 Atomic Scattering Factor	37
2.7.2 Structure Factor.....	38
2.8 XRD Equipment.....	43
2.8.1 X-Ray Source	44
2.8.2 The Specimen.....	45
2.8.3 X-Ray Detector.....	46
2.9 Examination of a Typical XRD Pattern	46
2.10 Crystal Structure Determination	48

2.11	Indexing the XRD Pattern.....	48
2.11.1	Comparison with a Calculated or Standard XRD Pattern	49
2.11.2	Relationship between $\sin^2 \theta$ and hkl Values.....	49
2.11.3	Analytical Approach	56
2.11.4	Identification of the Bravais Lattice	59
2.12	Differentiation between SC and BCC Lattices.....	61
2.13	Comparison with Electron and Neutron Diffraction.....	61
2.13.1	Electron Diffraction	63
2.13.2	Neutron Diffraction.....	65
2.14	Experimental Procedure.....	67
	Exercises.....	68
	Further Reading	70
Chapter 3	Optical Microscopy	71
3.1	Introduction	71
3.2	Principle of the Optical Microscope	73
3.3	Components of the Microscope.....	76
3.3.1	Light Source	76
3.3.1.1	Tungsten-Filament Lamp.....	76
3.3.1.2	Quartz-Halogen Lamp	76
3.3.1.3	Xenon Lamp	76
3.3.1.4	D.C. Carbon Arc.....	77
3.3.2	Lens Aberrations	78
3.3.3	Objective Lens.....	80
3.3.3.1	Types of Objective Lenses.....	80
3.3.3.2	Properties of Objective Lenses	82
3.3.4	Eyepiece	86
3.4	Microscopic Observation.....	86
3.5	Information Derivable from the Microstructure	90
3.5.1	Number of Phases.....	90
3.5.2	Grain Shape.....	92
3.5.3	Grain Size.....	94
3.5.4	Volume Fraction of Phases.....	98
3.5.5	Chemical Composition.....	99
3.6	Specimen Preparation for Microscopic Examination	100
3.6.1	Sectioning and Mounting	101
3.6.1.1	Sectioning	101
3.6.1.2	Mounting.....	101
3.6.2	Grinding	102
3.6.3	Polishing.....	103
3.6.4	Etching	105
3.7	Some Typical Microstructures	109
3.7.1	Nonferrous Alloy Samples	109
3.7.2	Ferrous Alloy Samples	113

3.8	Precautions	116
3.9	Experimental Procedure.....	117
	Exercises.....	120
	Further Reading	121
Chapter 4	Scanning Electron Microscopy	123
4.1	Introduction	123
4.2	Basic Design of the SEM.....	124
4.3	Electron Source	125
4.4	Electron Beam-Specimen Interactions	127
4.4.1	Secondary Electrons.....	128
4.4.2	Backscattered Electrons	129
4.4.3	X-Rays	130
4.5	Specimen Preparation.....	133
4.6	Applications.....	134
4.6.1	Fractography.....	134
4.6.2	Microstructural Features.....	136
4.7	Experimental Procedure.....	137
	Exercises.....	137
	Further Reading	138
Chapter 5	The Iron-Carbon Phase Diagram and Microstructures of Steels.....	139
5.1	Introduction	139
5.2	Phase Diagrams	140
5.3	Representation of Phase Diagrams.....	140
5.4	The Phase Rule.....	147
5.5	Application of the Phase Rule	149
5.5.1	Determination of Compositions of Phases	152
5.5.2	Determination of Amounts of Phases	154
5.6	Derivation of Lever Rule	155
5.7	The Iron-Carbon Phase Diagram	157
5.7.1	Solid Solubility Limits	159
5.7.2	Special Features of the Fe-C Phase Diagram.....	161
5.7.3	Invariant Reactions.....	162
5.8	Cooling Behavior and Microstructural Development	164
5.8.1	Hypoeutectoid (0.2 wt% C) Steel.....	164
5.8.2	Eutectoid (0.76 wt% C) Steel.....	173
5.8.3	Hypereutectoid (1.1 wt% C) Steel	175
5.9	Differentiation between Proeutectoid Ferrite and Proeutectoid Cementite.....	179
5.10	Microstructural Observation	181
5.11	Experimental Procedure.....	182
	Exercises.....	182
	Further Reading	184

Chapter 6	Heat Treatment of Steels	185
6.1	Introduction	185
6.2	Reaction Rates	186
6.2.1	Rate of Nucleation	189
6.2.2	Rate of Growth and Rate of Transformation.....	193
6.3	Isothermal Transformation Diagrams	194
6.4	Transformation Products	197
6.4.1	Pearlite.....	199
6.4.2	Bainite	200
6.4.3	Martensite.....	202
6.4.4	Morphology of Martensite	203
6.4.5	Mechanism of Martensite Formation.....	205
6.5	Retained Austenite	207
6.6	Isothermal Treatments.....	210
6.7	Effect of Alloying Elements on the <i>T-T</i> Diagram.....	210
6.8	Continuous Cooling Transformation Diagrams	212
6.9	Types of Heat Treatment	214
6.9.1	Annealing	216
6.9.2	Normalizing	219
6.9.3	Quenching	221
6.9.4	Tempering.....	223
6.10	Temper Embrittlement.....	225
6.11	Properties of Heat-Treated Steels	226
6.12	Experimental Procedure.....	228
	Exercises.....	230
	Further Reading	231
Chapter 7	Hardenability of Steels	231
7.1	Introduction	231
7.2	Definition of Hardenability	232
7.3	Distribution of Hardness	234
7.4	Severity of Quench	236
7.5	Grossmann Test	240
7.6	Jominy End-Quench Test.....	245
7.7	Parameters Affecting Hardenability	245
7.7.1	Austenitic Grain Size	248
7.7.2	Carbon Content	249
7.7.3	Alloying Elements.....	252
7.7.4	Use of Multiplying Factors.....	252
7.8	Jominy Tests and Continuous Cooling Transformation Diagrams	253
7.9	Hardness Tester to Be Used.....	253
7.10	Jominy Test for Nonferrous Alloys	255

7.11	Some Comments.....	255
7.12	Experimental Procedure.....	256
7.13	Results	257
7.14	Additional Experiment	257
	Exercises.....	258
	Further Reading	259
Chapter 8	Hardness Testing	261
8.1	Introduction	261
8.2	Types of Hardness Measurements	262
8.3	Scratch Hardness Measurement	262
8.4	Rebound Hardness Measurement.....	265
8.5	The Durometer Test.....	266
8.6	Indentation Hardness Measurement.....	268
8.7	Brinell Hardness Testing	268
8.7.1	Principle	268
8.7.2	Indenters and Loads	272
8.7.3	Hardness Designation.....	275
8.7.4	Advantages and Disadvantages	275
8.7.5	Precautions	275
8.7.6	General Observations	275
8.8	Rockwell Hardness Testing	276
8.8.1	Principle	276
8.8.2	Indenters and Loads	279
8.8.3	Rockwell Scales	280
8.8.4	Superficial Testing.....	282
8.8.5	Hardness Designation.....	282
8.8.6	Anvils	284
8.8.7	Precautions	284
8.8.8	Advantages and Disadvantages	285
8.9	Vickers Hardness Testing.....	285
8.9.1	Principle	286
8.9.2	Indenter.....	288
8.9.3	The Test	288
8.9.4	Hardness Designation.....	291
8.9.5	Precautions	291
8.9.6	Advantages and Disadvantages	292
8.10	Microhardness Testing	293
8.10.1	Principle	294
8.10.2	Indenters	295
8.10.3	The Test	295
8.10.4	Hardness Designation.....	297
8.10.5	Comparison between Vickers and Knoop Microindentation Tests	297
8.10.6	Precautions	297

8.11	Nanindentation Testing.....	297
8.11.1	Indenters and Loads	298
8.11.2	The Test.....	298
8.11.3	Analysis of Data.....	299
8.12	General Observations	301
8.12.1	Reproducibility	301
8.12.2	Surface Preparation	301
8.12.3	Minimum Thickness of Test Section	303
8.12.4	Minimum Spacing between Indentations.....	303
8.13	Correlations	303
8.13.1	Brinell versus Vickers Hardness Numbers.....	304
8.13.2	Relationship between Strength and Hardness.....	305
8.14	Experimental Procedure.....	307
8.15	Observations	309
8.16	Additional Experiments.....	310
8.16.1	Influence of Cold Working.....	311
8.16.2	Influence of Annealing on a Cold-Worked Metal	311
8.16.3	Influence of Alloying Additions.....	311
8.16.4	Microhardness of Different Phases	312
8.16.5	Influence of Aging on the Hardness of a Supersaturated Solid Solution Alloy	312
	Exercises.....	312
	Further Reading	313
Chapter 9	Tensile Testing.....	315
9.1	Introduction	315
9.2	Measurement of Strength	315
9.3	Basic Definitions.....	317
9.3.1	Stress	317
9.3.2	Strain	318
9.3.3	True Stress and True Strain.....	319
9.4	Deformation Behavior	321
9.4.1	Elastic Deformation.....	321
9.4.2	Plastic Deformation.....	323
9.4.3	Elastic Strain Recovery	323
9.4.4	Strain Hardening	324
9.4.5	Anelasticity.....	325
9.5	The Tensile Test.....	325
9.6	Properties Obtained from the Tensile Test.....	328
9.6.1	Proportional Limit.....	329
9.6.2	Yield Strength.....	329
9.6.3	Young's Modulus.....	331
9.6.4	Poisson's Ratio.....	335
9.6.5	Ultimate Tensile Strength.....	336

9.6.6	Necking	336
9.6.7	Fracture Strength.....	338
9.6.8	Ductility.....	338
9.6.9	Toughness	340
9.6.10	Resilience	341
9.7	True Stress versus True Strain Curve.....	342
9.8	General Observations	344
9.9	Influence of Variables on Tensile Properties.....	345
9.9.1	Chemical Composition	345
9.9.2	Microstructure.....	347
9.9.3	Temperature.....	348
9.9.4	Heat Treatment	350
9.9.5	Prior History of Plastic Deformation	350
9.9.6	Strain Rate.....	350
9.9.7	Anisotropy.....	352
9.10	Experimental Procedure.....	353
9.11	Observations	355
9.12	Results	355
9.13	Additional Experiment	355
	Exercises.....	356
	Further Reading.....	357
Chapter 10	Impact Testing.....	359
10.1	Introduction	359
10.2	Impact-Testing Techniques	360
10.2.1	Charpy Impact Test	360
10.2.2	Izod Impact Test.....	362
10.3	Ductile–Brittle Transition.....	363
10.4	Determination of Ductile–Brittle Transition Temperature.....	364
10.5	Effect of Variables on Impact Energy	369
10.5.1	Notch Sensitivity	369
10.5.2	Configuration of the Notch.....	370
10.5.3	Size of Specimen.....	371
10.5.4	Rate of Application of Energy.....	371
10.5.5	Crystal Structure of Material	371
10.5.6	Chemical Composition	373
10.5.7	Grain Size.....	373
10.5.8	Irradiation.....	373
10.5.9	Heat Treatment.....	374
10.6	Precautions	376
10.7	Correlations with Other Mechanical Properties.....	376
10.8	DBTT in Nonmetallic Materials	378
10.9	Experimental Procedure.....	378
10.10	Observations	379

Exercises.....	380
Further Reading	380
Chapter 11 Fatigue Testing	383
11.1 Introduction	383
11.2 Definitions	384
11.3 Fatigue Testing	387
11.4 Some Typical Examples of Fatigue Failure.....	391
11.5 Fatigue Failure Mechanism.....	396
11.6 Factors Affecting the Fatigue Strength of Materials.....	396
11.6.1 Stress Concentrators.....	396
11.6.2 Rough Surfaces	397
11.6.3 Surface Condition.....	397
11.6.4 Corrosion and Environmental Effects.....	398
11.7 Fracture Mechanics Approach	400
11.8 Correlations between Fatigue Strength and Other Mechanical Properties.....	407
11.9 Precautions	410
11.10 Experimental Procedure.....	410
11.11 Additional Experiments.....	411
Exercises.....	411
Further Reading	412
Chapter 12 Creep Testing.....	413
12.1 Introduction	413
12.2 The Creep Test.....	414
12.3 The Creep Curve	414
12.3.1 Primary or Stage I Creep	416
12.3.2 Secondary or Stage II Creep	416
12.3.3 The Tertiary or Stage III Creep.....	418
12.4 Effect of Stress and Temperature	419
12.5 Creep-Rupture Test.....	421
12.6 Creep Resistance Criteria.....	425
12.7 Larson–Miller Parameter	425
12.8 Creep in Ceramic Materials	428
12.9 Creep in Polymeric Materials.....	428
12.10 Experimental Procedure.....	429
Exercises.....	429
Further Reading	430