CONTENTS

EXI	ECUTI	VE SUMMARY	1	
	The Lesso	accidental exposure ons and recommendations	1 2	
1.	INTF	RODUCTION	7	
	1.1.	Background	7	
	1.2.	Objectives	9	
	1.3.	Scope	9	
	1.4.	Structure	9	
2.	BACKGROUND INFORMATION			
	2.1.	Radiotherapy departments in Panama	10	
	2.2.	The Radiotherapy Department at the Instituto Oncológico		
		Nacional	10	
		2.2 1 External beam radiotherapy	11	
		2.2.2. Brachytherapy	13	
	2.3.	Treatment planning system	14	
	2.4.	Radiation protection infrastructure and regulatory control	15	
		2.4.1. Authorization of the Radiotherapy Department	16	
	2.5.	History of recent audits of the Radiotherapy Department	16	
		2.5.1. Audit in February 1999	16	
		2.5.2. Audit in February 20012.5.3. Results of IAEA/WHO TLD postal dose quality audits	18	
		performed at the ION	19	
3.	THE	ACCIDENTAL EXPOSURE	19	
	3.1.	Initiating event	19	
	3.2.	Discovery of the problem	23	
4	RES	PONSE TO THE ACCIDENTAL EXPOSURE	24	
	4.1.	Actions taken upon discovery of the error	24	
	4.2.	Response from the IAEA	25	

5.	DOS	E ASSESSMENT	28		
	5.1.	Introduction	28		
	5.2.	Scope of the dosimetric evaluation	29		
	5.3.	Comparison of the dosimetry systems and beam calibration	31		
		5.3.1. Dosimetry system intercomparison	31		
		5.3.2. ⁶⁰ Co beam calibration	32		
		5.3.3. Variation of absorbed dose with field size	32		
		5.3.4. Depth dose data	33		
		5.3.5. Wedge transmission	33		
		5.3.6. Verification of dose delivery	33		
	5.4.	Patient doses	34		
		5.4.1. Assessment of doses from irradiation with external beams	34		
		5.4.2. Consideration of brachytherapy treatments	35		
		5.4.3. Doses equivalent to treatments of 2 Gy per fraction	35		
		5.4.4. Other patients treated in the same period	46		
6.	TEST OF THE COMPUTER SOFTWARE USING DIFFERENT				
	APP:	ROACHES FOR DATA ENTRY	47		
	6.1.	Instructions and warnings	47		
	6.2.	Tests performed	48		
7.	MEI	DICAL ASSESSMENT	60		
	7.1.	Background information on radiation effects in humans	60		
	7.2.	Basic radiotherapy principles relevant to this accidental exposure .	61		
	7.3.	Fractionation of radiation exposure	62		
	7.4.	Adverse effects	62		
	7.5.	Spectrum of overexposures in this event	63		
	7.6.	Complicating factors in the evaluation of this event	65		
	7.7.	Results of the medical team's investigation	65		
		7.7.1. Surviving patients	72		
		7.7.2. Deceased patients	75		
		7.7.3. Sequence of events leading to death	78		
8.	FINDINGS AND CONCLUSIONS OF THE TEAM,				
	ANI	D LESSONS TO BE LEARNED	79		
	8.1.	Operating organization: Radiotherapy departments	80		
		8.1 .1. Quality assurance and radiotherapy	80		

	8.1.2. Treatment planning systems as a safety issue	81
		8 1
	8.1.4. Changes in procedures	81
	8.1.5. Workload and team integration	82
	8.1.6. Observation of unusual reactions of patients	82
	8.1.7. In vivo dosimetry	83
	8.1.8. Local advice from the manufacturer/supplier	83
8.2.	National authorities	83
	8.2.1. Quality assurance	83
	8.2.2. Communication between regulators and users of radiation .	84
8.3.	Equipment manufacturers and suppliers	84
	8.3.1 Software in treatment planning	84
8.4.	The medical community	85
	8.4.1. Findings	85
	8.4.2. Recommendation on patient care and follow-up	85
ANNEX I.	TERMINATION REPORT TO THE CONTACT POINTS	87
ANNEX II	. LITERATURE REVIEW OF RADIATION EFFECTS IN	
	PERTINENT TISSUES IN THIS ACCIDENTAL EXPOSURE	89
		89
	stine	90
_	moid and rectum	92
Bladder		93
Uterus		95
Vagina .		96
Prostate ar	nd seminal vesicles	97
Penis, uret	hra and scrotum	97
ANNEX I	II. DATA ON INDIVIDUAL PATIENTS INVOLVED IN THIS	
	ACCIDENTAL EXPOSURE	99
REFEREN		
CONTRIE	BUTORS TO DRAFTING AND REVIEW	115