

Contents

Preface XVII

List of Contributors XXI

Part I General 1

1 Microstructure and Properties of Engineering Materials 3

Helmut Clemens and Christina Scheu

- 1.1 Introduction 3**
- 1.2 Microstructure 5
- 1.2.1 Crystal Defects 8
- 1.2.2 Grain (Phase) Boundaries and Twins 8
- 1.2.3 Precipitates and Dispersions 9
- 1.3 Microstructure and Properties 12
- 1.4 Microstructural Characterization 15

References 20

2 Internal Stresses in Engineering Materials 21

Anke Rita Pyzalla

- 2.1 Definition 21**
- 2.1.1 Stress Tensor, Strain Tensor, and Elasticity Tensor 21
- 2.1.1.1 Stress Tensor 21
- 2.1.1.2 Strain Tensor 22
- 2.1.2 Definitions, Residual Stresses 24
- 2.1.2.1 Stress Equilibrium 24
- 2.1.2.2 Residual Macro- and Microstresses 25
- 2.2 Origin of Residual Macro- and Microstresses 27
- 2.2.1 Residual Stress Formation in Primary Forming Processes 29
- 2.2.2 Residual Stress Formation in Heat Treatment Processes 30
- 2.2.2.1 Residual Stresses in a Material without Phase Transformation (Pure Cooling Residual Stresses) 30

6.8	Experimental Set-up and Measuring Procedures	130
6.8.1	Experimental Set-up	130
6.8.1.1	Diffractometers	130
6.8.1.2	Diaphragms	132
6.8.1.3	Detectors	132
6.8.2	Measuring Procedures	132
6.9	Overview on In-depth and Local Residual Stress Analysis	133
	References	134
7	Stress Analysis by Angle-Dispersive Neutron Diffraction	137
	<i>Peter Staron</i>	
7.1	Introduction	137
7.2	Diffractometer for Residual Stress Analysis	138
7.2.1	Set-up of a Diffractometer for Strain Scanning	138
7.2.2	Monochromator	139
7.2.3	Slit System	140
7.2.4	Sample Positioning	141
7.2.5	Detector	141
7.3	Measurement and Data Analysis	142
7.3.1	Gauge Volume and Sample Positioning	142
7.3.2	Data Reduction and Analysis	144
7.3.2.1	Data Reduction and Peak Fitting	144
7.3.2.2	Calculation of Stresses	145
7.3.2.3	Macro and Microstresses	147
7.3.2.4	Stress-Free Reference	147
7.4	Examples	148
7.4.1	Residual Stresses in Friction Stir Welded Aluminum Sheets	148
7.4.2	Residual Stresses in Water-Quenched Turbine Discs	150
7.5	Summary and Outlook	152
	References	152
8	Stress Analysis by Energy-Dispersive Neutron Diffraction	155
	<i>Javier Roberto Santisteban</i>	
8.1	Introduction	155
8.2	Time-of-Flight Neutron Diffraction	155
8.2.1	TOF Peak Shape and Data Analysis Packages	157
8.3	TOF Strain Scanners	159
8.3.1	Counting Times and Resolution	160
8.3.2	Neutron Optics and Time Focusing	163
8.4	A Virtual Laboratory for Strain Scanning	164
8.5	Evolution of Intergranular Stresses	168
8.6	TOF Transmission Analysis	170
8.6.1	Bragg Edges	171

8.6.2	Strain Mapping	172
8.6.3	Quantitative Phase Analysis	172
8.6.4	Other Applications	174
8.7	Conclusions	174
	<i>References</i>	175

9 Residual Stress Analysis by Monochromatic High-Energy X-rays 177

Rene Valery Martins

9.1	Basic Set-ups	177
9.2	Principle of Slit Imaging and Data Reconstruction	180
9.3	The Conical Slit	181
9.3.1	Working Principle	181
9.3.2	Capabilities	182
9.3.3	Example	183
9.4	The Spiral Slit	184
9.4.1	Functional Principle	184
9.4.2	Capabilities	186
9.4.3	Example	186
9.5	Simultaneous Strain Measurements in Individual Bulk Grains	188
9.6	Coarse Grain Effects	189
9.7	Analysis of Diffraction Data from Area Detectors	191
9.8	Matrix for Comparison and Decision Taking Which Technique to Use for a Specific Problem	193
	<i>References</i>	193

10 Residual Stress Analysis by White High Energy X-Rays 195

10.1 Reflection Mode 195

Christoph Genzel

10.1.1	Motivation	195
10.1.2	Basic Relations in Depth-Resolved Energy-Dispersive X-Ray Stress Analysis (XSA) in Reflection Geometry	196
10.1.3	Experimental Set-up	199
10.1.4	Example for Depth-Resolved Residual Stress Analysis by ED Diffraction	200
10.1.5	Concluding Remarks and Prospects	205
	<i>References</i>	206

10.2	Transmission Mode	207
<i>Anke Rita Pyzalla</i>		
10.2.1	Motivation	207
10.2.2	Experiment Set-up and Experimental Details	208
10.2.2.1	Penetration Depth	208
10.2.2.2	Gauge Volume and Spatial Resolution	209
10.2.2.3	Example for an Experiment Set-up	211
10.2.3	Data Evaluation	213
10.2.4	Examples	214
10.2.5	Conclusions	218
<i>References</i>		218
11	Diffraction Imaging for Microstructure Analysis	221
<i>Thomas Wroblewski</i>		
11.1	Introduction, the Principle of Diffraction Imaging	221
11.2	The MAXIM Experiment at HASYLAB Beamline G3	222
11.3	Data Structure	223
11.4	Strategies for Data Reduction and Visualization	224
11.5	Outlook, Bulk Imaging	226
<i>References</i>		228
12	Basics of Small-Angle Scattering Methods	229
<i>Philipp Klaus Pranzas</i>		
12.1	Common Features of a SAS Instrument	229
12.2	Contrast	230
12.3	Scattering Curve	230
12.4	Power Law/Scattering by Fractal Systems	232
12.5	Guinier and Porod Approximations	233
12.6	Macroscopic Differential Scattering Cross Section	234
12.7	Model Calculation of Size Distributions	235
12.8	Magnetic Structures	236
<i>References</i>		237
13	Small-Angle Neutron Scattering	239
<i>Philipp Klaus Pranzas</i>		
13.1	Nanocrystalline Magnesium Hydride for the Reversible Storage of Hydrogen	240
13.2	Precipitates in Steel	242
13.3	SiO ₂ Nanoparticles in a Polymer Matrix - an Industrial Application	245
13.4	Green Surfactants	246
<i>References</i>		248

14	Decomposition Kinetics in Copper-Cobalt Alloy Systems: Applications of Small-Angle X-ray Scattering	249
	<i>Giinter Goerigk</i>	
14.1	Introduction	249
14.2	ASAXSFundamentals	249
14.3	Results of ASAXSExperiments Characterizing the Decomposition in Copper-Cobalt Alloys	252
14.4	Outlook	255
14.5	Summary	255
	<i>Riferences</i>	256
15	B3 Imaging	257
	<i>Wolfgang Treimer</i>	
15.1	Radiography	257
15.1.1	Fundamentals	257
15.1.2	Interactions of Neutrons with Matter	259
15.1.3	Geometries	261
15.1.4	Resolution Functions	264
15.1.5	Image Degradation	267
15.1.6	Other Imaging Techniques	269
15.2	Tomography	274
15.2.1	Mathematical Introduction	274
15.2.2	Slice Theorem, Shannon Theorem	276
15.2.3	Image Reconstruction	277
15.3	New Developments in Neutron Tomography	281
	<i>References</i>	285
16	Neutron and Synchrotron-Radiation-BasedImaging for Applications in Materials Science - From Macro- to Nanotomography	287
	<i>Felix Beckmann</i>	
16.1	Introduction	287
16.1.1	Attenuation-Contrast Projections	287
16.1.2	Phase-Contrast Projections	288
16.1.3	Phase-Enhanced Projections	289
16.1.4	Direct Phase-Contrast Projections	289
16.1.5	Indirect Phase-Contrast Projections	290
16.2	Parallel-BeamTomography	290
16.2.1	Measurement and Reconstruction	291
16.2.2	Density Resolution and Detector Quality	292
16.2.3	Data Evaluation and Visualization	295
16.3	Macrotomography Using Neutrons	296
16.3.1	Experimental Set-up	296

16.3.2	Measurements and Results	297
16.4	Microtomography Using Synchrotron Radiation	300
16.4.1	Beamline Optics	300
16.4.2	Experimental Set-up	301
16.5	Summary and Outlook	306
	<i>References</i>	306

17 *μ-Tomography of Engineering Materials* 309*Astrid Haibel*

17.1	Advantages of Synchrotron Tomography	309
17.2	Applications and 3D Image Analysis	310
17.2.1	Discharging Processes in Alkaline Cells	310
17.2.2	Microstructural Investigations of Nb ₃ Sn Multifilamentary Superconductor Wires	312
17.2.3	Influence of the Foaming Agent on Metallic Foam Structures	314
17.3	Image Artifacts	316
17.3.1	Ring Artifacts	316
17.3.2	Image Noise	317
17.3.3	Edge Artifacts	318
17.3.4	Motion Artifacts	318
17.3.5	Centering Errors of the Rotation Axis	319
	<i>References</i>	320

18 *Diffraction Enhanced Imaging* 323*Michael Lohmann*

18.1	Introduction	324
18.1.1	Basics	324
18.1.2	Extinction Contrast	325
18.1.3	Principles of DEI	326
18.2	Experimental Set-up	328
18.3	Examples	329
18.3.1	Complete Set of DEI Images	329
18.3.2	Material Science	329
18.3.3	Example of Mineralogical Investigations	331
18.4	Conclusions	332
	<i>References</i>	332

Part III New and Emerging Methods 333

19	3D X-ray Diffraction Microscope	335
	<i>Henning Friis Poulsen, Wolfgang Ludwig, and Søren Schmidt</i>	
19.1	Basic Set-up and Strategy	336
19.1.1	The 3DXRD Microscope	338
19.2	Indexing and Characterization of Average Properties of Each Grain	339
19.2.1	Application I: Nucleation and Growth Studies	340
19.2.2	Application II: Plastic Deformation	341
19.2.3	Application III: Studies of Subgrains and Nanocrystalline Materials	342
19.3	Mapping of Grains and Orientations	343
19.3.1	Mode III: Mapping Grains in Undeformed Specimens	343
19.3.2	Mode IV: Mapping Orientations in Deformed Specimens	345
19.3.3	Application I: Recrystallization	346
19.3.4	Application II: Grain Growth	347
19.4	Combining 3DXRD and Tomography	348
19.4.1	Grain Mapping by Tomography	349
19.5	Outlook	350
	<i>References</i>	350
20	3D Micron-Resolution Laue Diffraction	353
	<i>Gene E. Ice</i>	
20.1	Introduction	353
20.1.1	The Need for <i>Polychromatic</i> Microdiffraction	353
20.2	Theoretical Basis for Advanced Polychromatic Microdiffraction	355
20.2.1	Modified Ewald's Sphere Description of Laue Diffraction	355
20.2.2	Qualitative Information: Phase, Texture, Elastic Strain, Dislocation Density	356
20.2.2.1	phase	356
20.2.2.2	Texture	357
20.2.2.3	Dislocation Tensor	357
20.2.2.4	Elastic Strain Tensor	357
20.3	Technical Developments for an Automated 3D Probe	357
20.3.1	Source	358
20.3.2	Microbeam Monochromator	359
20.3.3	Nondispersive Focusing Optics	361
20.3.4	Area Detector	361
20.3.5	Differential Aperture	361
20.3.6	Software	362

20.4	Research Examples	363
20.4.1	3D Grain Boundary Networks	363
20.4.2	Deformation Behavior and Grain Boundaries	364
20.4.3	Deformation in Single Crystals	365
20.4.4	Grain Growth on Surfaces and in Three-Dimensions	366
20.4.5	Anomalous Grain Growth	367
20.5	Future Prospects and Opportunities	369
	<i>RrifCrences</i>	370
21	Quantitative Analysis of Three-Dimensional Plastic Strain Fields Using Markers and X-ray Absorption Tomography	371
	<i>Kristoffer Haldrup and John A. Wert</i>	
21.1	Introduction	371
21.2	Experimental Approach	372
21.2.1	Markers	372
21.2.2	Particle Tracking and DGT Calculation	372
21.2.3	Spatial Resolution	373
21.3	Results of Investigations	373
21.3.1	Homogeneous Deformation	373
21.3.2	Heterogenous Deformation	374
21.3.3	Microstructural Effects	375
21.4	Outlook	376
	<i>RrifCrences</i>	377
22	Combined Diffraction and Tomography	379
	<i>Anke Rita Pyzalla and Augusta Isaac</i>	
22.1	Introduction	379
22.2	Experimental Set-up	380
22.3	Example: Combined Diffraction and Tomography for Investigating Creep Damage Evolution	381
22.3.1	Scientific Background	381
22.3.2	Experimental Details	381
22.3.2.1	Miniature Creep Device	381
22.3.2.2	Tomography and Diffraction	381
22.3.2.3	Material	382
22.3.3	Results	382
22.4	Conclusions and Outlook	385
	<i>Refrences</i>	386

Part IV Industrial Applications 387**23 Diffraction-Based Residual Stress Analysis Applied to Problems
in the Aircraft Industry 389**

*Peter Staron, Funda S. Bayraktar, Mustafa Koqak, Andreas Schreyer,
Ulrike Cihak, Helmut Clemens, and Martin Stockinger*

- 23.1 Motivation 389
- 23.2 Residual Stresses in Turbine Disks 390
 - 23.2.1 Introduction 390
 - 23.2.2 Material 391
 - 23.2.3 Finite Element Modeling 393
 - 23.2.4 Neutron Diffraction 395
 - 23.2.5 Results 396
 - 23.2.5.1 *In Situ* Tensile Test 396
 - 23.2.5.2 Stresses in a Turbine Disk 397
 - 23.2.5.3 Stresses in a Thin Plate 398
 - 23.2.6 Summary 400
- 23.3 Residual Stresses in Laser-Welded Al Joints 400
 - 23.3.1 Introduction 400
 - 23.3.2 Materials and Welding 401
 - 23.3.3 Neutron Diffraction 404
 - 23.3.4 Stresses in Laser-Welded T-Joints 405
 - 23.3.5 Stresses in Laser-Welded Butt Joints 407
 - 23.3.6 Summary 408
- 23.4 Conclusions 409
 - References 410

24 Optimization of Residual Stresses in Crankshafts 413

Anke Rita Pyzalla

- 24.1 Introduction 413
- 24.2 Experimental Determination of Residual Stresses in Crankshafts 414
- 24.3 Experimental Results and Implications 416
- 24.4 Conclusions 418
 - References 419

Index 421