

CONTENTS

1.	INTRODUCTION	1
1.1.	Background	1
1.2.	Objective	2
1.3.	Scope	2
1.4.	Structure	3
2.	BACKGROUND INFORMATION	3
2.1.	Radiation protection infrastructure	3
2.2.	The licensed hospital	5
2.3.	The non-licensed supplier	5
2.4.	The device and its source	7
3.	THE ACCIDENT	8
3.1.	Description of the accident	8
3.2.	Discovery and notification	12
3.3.	Response and recovery	15
3.4.	Involvement of the IAEA	21
4.	RADIOPATHOLOGICAL CONSIDERATIONS	22
4.1.	General	22
4.2.	Treatment and clinical progression of patients in Group 1 (P1-P4)	24
4.3.	Treatment and clinical progression of patients in Group 2 (P5-P10)	33
4.4.	Chromosomal study	40
5.	FINDINGS, CONCLUSIONS AND LESSONS TO BE LEARNED	40
5.1.	Operating organizations	42
5.2.	National authorities	43
5.3.	International co-operation	46
5.4.	Equipment suppliers	47
5.5.	The medical community	48
	REFERENCES	50
	CONTRIBUTORS TO DRAFTING AND REVIEW	52